

PREVOST

MAINTENANCE INFORMATION

MI25-07

DATE: March 2025 SECTION: 12 BRAKE & PNEUMATIC SUBJECT: NEW BRAKE PAD REGULATIONS IN

CALIFORNIA & WASHINGTON STATE

First Release 03-25-2025

APPLICATION

Model	VIN	VIN. GREGISTANCE OR CANADA PREVOST CARRING. TE CLAMFORMETTE GR. CAMADA
H3-45 coaches Model Year : 2025 - today		From 2P9H33499SC001279 up to today
H3-45 VIP motorhomes Model Year : 2025 - today		From 2P9VS3490SC110025 up to today
X3-45 coaches Model Year : 2025 - today		From 2P9G33497SC001650 up to today
X3-45 VIP commercial use Model Year : 2025 - today		From 2P9CS3496SC110697 up to today
X3-45 VIP motorhomes Model Year : 2025 - today		From 2P9BS3493SC110698 up to today

DESCRIPTION

This maintenance information is to inform you of the new **Better Brake Rule 2025** regulations which started to be enforced in California and Washington State on **January 1**, **2025**. These new rules will have a direct impact on the brake pads installed on Prevost vehicles sold or repaired in California and Washington State. This regulation **only applies to vehicles manufactured after January 1st, 2025**. The new rule significantly reduces the allowable copper content in brake pads, limiting it to no more than 0.5% (Level-N). We need to ensure that any brake pads are compliant with this new copper limit. Starting January 1st, 2025, all brake pads sold in California and Washington State for vehicles manufactured after January 1st, 2025, must adhere to these updated standards. This includes both OEM and aftermarket brake pads.

- For all vehicles manufactured after January 1st, 2025 using the Knorr SN7 brakes, **the brake pads Level-N 610079 must be installed in replacement of the Level-B 610072**. They will be available in our Service Centers in California.
- For vehicles X3-45VIP, starting in January 2025 with the introduction of the new IFS, we will be using a different OEM supplier (Meritor) for the front axle brakes, while the rear axle will continue to use the same Knorr SN7 brakes. The brake pads Level-N 24577901 must be installed on the Meritor front axle calipers.

Writer: JPHD <QF7720955 rev 7>

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ Or scan the QR-Code with your smart phone

Are you a Vehicle owner?

E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.



Writer: JPHD <QF7720955 rev 7>