




H3-45, H3-41 BUS



REV	DATE	O.C.	EFF.	DESCRIPTION	PAGE(S)	BY	CK.	APPR.
00	2009/10	2010001	A-1573	Preliminary vehicle	All	E.O	C.L	C.L
01	2010-11-01	2010001	A-1721	Remove entrance door unlock sensor	0, 29.1	MP	C.L.	C.L.
02	2011-01-17	2010039	B-1786	Relocate YAW sensor in Fr wheels	C1,16.2	E.L.	E.L.	C.L.
03	2011-07-15	2010119	C-1912	Replace Power Relays 70 Amp General Update	0,A,C1,K,3.3,22.1 L,30.3	E.L.	E.L.	C.L.
3-1	2011-07-25	2011015	C-1949	Electrical Driver's Seat	14.1,18.2, C1, 0	SB	CL	CL
3-2	2011-08-15	2011014	C-1965	C1 Updated	0, C1	SB	CL	CL
04	2011-08-23	2011106	C-2007	Knelling level sensor	32.1	MPOU	CL	CL
05	2011-09-13	2011003	C-2007	Replace MasterID and CECM by MCM	7.1, C1	SD	DG	DG
06	2011-12-14	2011057		2011_Q4 TGW, New Pwr and Ground ACM, new gnd on DPF Temp Sensor, MasterId removed C-1978 Preliminary C-2046 Preliminary C-2048 Preliminary C-2052 Preliminary C-2054 Preliminary C-2059 Production	B, C1, E, F, G, H, J, K, L, 1.1, 2.1, 3.1, 3.3, 4.1, 5.1, 6.1, 6.2, 7.1, 14.1, 14.5, 32.1, 37.1	PG	DG	DG
07	2012-03-20	2012020	C-2164	2012_R1 ESP STD, WIRES NETWORK	5.1,6.1, 7.1, 8.1, 10.1, 13.1, 14.1, 14.2, 14.5, 15.3, 16.1, 33.1, 35.6, 36.1, 37.1, 39.1, 41.1, C1, C3, E, 0, A	SB	CL	CL
08	2012-03-27	2012030	C-2266	2012_R2 Interior led lighting	A, 0, 2.1, 5.1, 20.1, 23.1, 24.1 end for 21.1	MPOU	CLEM	CLEM
09	2012-10-19	2012030	C-2266	Add direct led rear extension C583R	0, 24.1, C1	MPOU	CLEM	MPOU



H3-45, H3-41 BUS



REV.	DATE	O.C.	EFF.	DESCRIPTION	PAGE(S)	BY	CK.	APPR.
10	2012-12-07	2012048	D-2272	Pages Updated	0, 3.2, C1	SB	C.L.	C.L.