



XLII SHELL



REV.	DATE	O.C.	EFF.	DESCRIPTION	PAGE(S)	BY	CK.	APPR.
0	2010-12-21	2010001		EFF:9971		E.O	C.L	C.L
01	2011-02-01	2010089		REMOVE ENGINE LIGHT SWITCH ADD PROXIMITY SENSOR ON ENGINE DOOR	0, 18.2, 25.1	M.P.	C.L.	C.L.
02	2011-02-21	na		move ground on gateway	0, 32.1	M.P.	C.L.	C.L.
03	2011-07-19	2010039 2011015 2010119	C-5087 C-5134 B-5050	Relocate YAW sensor in Fr wheels Replace Power Relays 70 Amp Electrical Driver's Seat General Update	16.2 0,A,C1,K,3.3 L, 2.1, 4.1, 30.3 G, 5.1,14.2	E.L.	E.L.	C.L.
04	2011-09-13	2011003	C-5160	Replace MasterID and CECM by MCM	0,7.1	S.D.	DG	DG
05	2011-12-01	2011057 2011107 2011047 2011086	C-5265 SAME SAME SAME	TGW Gnd & Pwr of ACM SEPARATE HARNESS FOR EVAP&COND Relocation AFSS TANK General Update	11.1, 4.1, 6.2, 2.1, 16.1 3.1, 3.2, 3.3, 14.1, 14.5, 5.1 7.1, 6.1, 10.1, 18.2, 26.2 35.1 A, B1, B2, B3, C1, E, F, G, H, J, K, L	P.G. S.B. M.P. S.B. S.B.	C.L.	C.L.
06	2012-03-22	2012020		2012_R1 ESP STD, WIRES NETWORK	A, 5.1, 6.1, 8.1, 10.1, 20.1, 32.1, 33.1 13.1, 14.1, 14.2, 14.5, 15.1, 16.1, 0, C1, C3, E.	S.B	C.L	C.L
07	2012-07-20	2012097		reverse Mo26 and modify luggage doors locks switches	0, 24.1, 29.1	M.P.	C.L.	C.L.
08	2014-05-12	NA		Pages Update	0,3.2	S.B.	C.L.	C.L.