

0

1

2

3


4

Windows ajar

A

A


Magnetic sensors window ajar RH



B

B

Magnetic sensors window ajar LH



C

C

D

D

E

E

0

1

2

3

4