

APPLICATION:

Model	VIN	
H3 coaches * Model Year: 1995 - 1998		From 2P9H33415 <u>S</u> 1001 <u>284</u> up to 2PCH33490 <u>W</u> 101 <u>2358</u> incl.
XL coaches * Model Year: 1995 - 1998		From 2P9L33490 <u>S</u> 1001 <u>497</u> up to 2PCM33492 <u>W</u> 102 <u>6504</u> incl.

*NOTE:

A warranty bulletin (96-06A) was distributed in 1996 concerning some 1995 et 1996 vehicles which fuel tank suction hoses are rigid, revealing that these suction hoses must be changed. If this change has never been executed, it will be necessary to do it simultaneously with the installation of the part of which this publication concern.

DESCRIPTION

It is possible to run out of fuel when the preheat system is maintained effective for a prolonged period. The accessories working on the fuel tank auxiliary connection can also be the source of this problem.

The installation of a fastener over the suction hoses provides two (2) main advantages:

- 1. A fuel reserve for the engine group when the preheat system or the accessories ran out of their fuel reserve.
- 2. The suction hose efficiency warranty in spite of the limitation of their movement inside the fuel tank.

MATERIAL

Part No.	Description	Qty
032240	Complete suction hose bracket kit (Instruction sheet included).	1

Note: Material can be obtained through regular channels.