

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
120V_inlet	RearVehicle	561572	male	A34.7	EngineCmpt.	564258	male
A1	RJB	563975	male	A34.8	EngineCmpt.	564258	male
A2	FJB	563984	male	A34.J	Enginecmpt.	568118	male
A3	Dash	562363	male	A34.K	Enginecmpt.	564270	male
A4.A	Service_Cmpt	562428	female	A34.L	Enginecmpt.	564269	male
A4.B	Service_Cmpt	561188	female	A36.JA	FJB	562767	male
A5	Service_Cmpt	562428	female	A36.JB	FJB	562765	male
A6	Engine_Cmpt	562427	male	A36.JC	FJB	562957	male
A7	Rear_Axle_Cmpt	563979	male	A39.P101	Parcelrack	563201	male
A9.Cx1	FJB	564041	female	A39.P901	Parcelrack	563953	male
A9.Cx2	FJB	563678	male	A40.A	FJB	561668	male
A9.Cx3	FJB	564037	female	A60.A	Parcelrack	563071	male
A9.Cx4	FJB	564038	female	A60.B	Parcelrack	562706	female
A10.X1	Engine_Cmpt	563135	male	A60.C	Parcelrack	901110	male
A10.X3	Engine_Cmpt	563134	female	A60.D	Parcelrack	901110	male
A11	LH_Console	563142	male	A61.A	Parcelrack	562464	male
A14.A	Dash	562766	male	A61.B	Parcelrack	562465	male
A14.B	Dash	562767	male	A65.B	Parcelrack	901110	male
A14.C	Dash	562765	male	A65.C	Parcelrack	901110	male
A15	Dash	562464	male	A65.Csv	Parcelrack	562465	male
A17.D	RJB	561932	male	A65.D	Parcelrack	901110	male
A18.J1	FJB	562794	male	A69.A	Parcelrack	563071	male
A18.J2	FJB	562650	male	A69.B	Parcelrack	561716	female
A19	LH_Console	562878	female	A69.C	Parcelrack	561716	female
A20	Parcel_Rack_LH	561477	female	A69.D	Parcelrack	561716	female
A24.A	RH_Console	561890	male	A69.E	Parcelrack	561716	female
A24.B	RH_Console	561566	female	A69.F	Parcelrack	561716	female
A24.C	RH_Console	561889	female	A69.G	Parcelrack	561716	female
A25	Parcelrack	563025	male	A69.H	Parcelrack	561716	female
A26.P1	Enginecmpt.	562350	male	A70c	Parcelrack	561540	female
A26.P2	Enginecmpt.	563322	female	A77	Parcelrack	564547	male
A26.P4	Enginecmpt.	568088	male	A78	Parcelrack	562583	female
A27	Service_Cmpt	562929	male	A79	Parcelrack	562583	female
A28	Service_Cmpt	562928	male	A80	Parcelrack	562479	female
A29	Dash	562464	male	A81.JA	FJB	562767	male
A33.A	Parcelrack	563071	male	A81.JB	FJB	562765	male
A33.B	Parcelrack	562330	female	A81.JC	FJB	562957	male
A34.1	EngineCmpt.	564258	male	A83	Parcelrack	565970	female
A34.2	EngineCmpt.	564258	male	A84.A	Parcelrack	563071	male
A34.3	EngineCmpt.	564258	male	A96	FJB	564073	female
A34.4	EngineCmpt.	564258	male	A97	Dash	563226	male
A34.5	EngineCmpt.	564258	male	A97A	FJB	563226	male
A34.6	EngineCmpt.	564258	male	A97A	FJB	563613	female

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
A97B	FJB	563226	male	AE42.J2	FJB	564037	female
A97B	FJB	563613	female	AE42.J3	FJB	564004	male
A97S.A1	Dash	564401	male	AE43.J1	FJB	563679	male
A97S.A3	Dash	564403	male	AE43.J2	FJB	564037	male
A99	FJB	564205	male	AE43.J3	FJB	565957	male
A100	Front_Axle_Cmpt	563758	female	AE44.J1	FJB	563679	male
A101	Rear_RH_Axle_Cmpt	563758	female	AE44.J2	FJB	564037	female
A102	Rear_RH_Axle_Cmpt	563758	female	AE44.J3	FJB	565957	male
A103	Dash	562070	female	AE45.J1	FJB	563679	male
A107	EngineCmpt.	560336	male	AE45.J2	FJB	564037	female
A108	RJB	562766	male	AE45.J3	FJB	565957	male
A109A	FJB	564141	male	AE46.J1	FJB	563679	male
A113.A	Parcel_Rack_LH	563960	male	AE46.J2	FJB	564037	female
A113.B	Parcel_Rack_LH	563962	male	AE46.J3	FJB	565957	male
A113.C1	Parcel_Rack_LH	563956	male	AE47.J1	RH_console	563679	male
A113.C2	Parcel_Rack_LH	563957	male	AE47.J2	RH_console	564037	female
A113.C3	Parcel_Rack_LH	563958	male	AE47.J3	RH_console	565957	male
A114A	Dash	564252	male	AE48.J1	RH_console	563679	male
A120.A	Dashboard	563960	male	AE48.J2	RH_console	564037	female
A120.B	Dashboard	563962	male	AE48.J3	RH_console	565957	male
A120.C1	Dashboard	563956	male	AE49.J1	RJB	563679	male
A120.C2	Dashboard	563957	male	AE49.J2	RJB	564037	male
A120.C3	Dashboard	563958	male	AE49.J3	RJB	565957	male
A121.Vsa	Dash	563679	male	AE50.J1	RJB	563679	male
A121.Vsb	Dash	563678	male	AE50.J2	RJB	564037	male
A121.Vsc	Dash	564037	male	AE50.J3	RJB	565957	male
A121.Vsd	Dash	564118	male	AE51.J1	RJB	563679	male
A130	Driver_Area	563226	male	AE51.J2	RJB	564037	female
A131.A	Engine_Cmpt	561782	male	AE51.J3	RJB	565957	male
A131.B	Engine_Cmpt	561781	female	AE52.J1	RJB	563679	male
A137A	Condensercmpt.	20429843	male	AE52.J2	RJB	564037	female
A138	Cond_Cmpt	563787	male	AE52.J3	RJB	565957	male
A139	Dash	564501	male	AE53.J1	RJB	563679	male
A151.A	Parcelrack	561582	female	AE53.J2	RJB	564037	female
A151.B	Parcelrack	561582	female	AE53.J3	RJB	565957	male
A152.J	Parcelrack	563071	male	AE54.J1	Evaporatorcmpt.	563679	male
A153.A	Parcelrack	562465	male	AE54.J2	Evaporatorcmpt.	564037	female
A160.A	WCLcmpt	562477	male	AE54.J3	Evaporatorcmpt.	565957	male
A160.B	WCLcmpt	562884	female	AE55.J1	Dash	563679	male
AE41.J1	FJB	563679	male	AE55.J2	Dash	564037	female
AE41.J2	FJB	564037	female	AE55.J3	Dash	564004	male
AE41.J3	FJB	564004	male	AE56.J1	Dash	563679	male
AE42.J1	FJB	563679	male	AE56.J2	Dash	564037	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
AE56.J3	Dash	564004	male	C55	FJB	563589	male
AE57.J1	WCLcmpt.	563679	male	C55	FJB	563590	female
AE57.J2	WCLcmpt.	564037	male	C6	FJB	563582	male
AE57.J3	WCLcmpt.	564004	male	C6	FJB	563583	female
Alt_LL.A	Enginectpt.	563746	female	C7	Service_Cmpt	562566	male
Alt_LL.B	Enginectpt.	560815	female	C7	Service_Cmpt	562565	female
Alt_LL.C	Enginectpt.	564469	female	C8	FJB	563227	male
Alt_LR.A	enginectpt.	563746	female	C8	FJB	563614	female
Alt_LR.B	Enginectpt.	560815	female	C9	RJB	561986	male
Alt_LR.C	Enginectpt.	564469	female	C9	RJB	561987	female
Alt_UR.A	Enginectpt.	563746	female	C10	Engine_Cmpt	562477	male
Alt_UR.B	Enginectpt.	560815	female	C10	Engine_Cmpt	562479	female
Alt_UR.C	Enginectpt.	564469	female	C11	Service_Cmpt	563580	male
B85	Engine_Cmpt	563815	male	C11	Service_Cmpt	563581	female
B96	Engine_Cmpt	563821	male	C12	Engine_Cmpt	562581	male
B96B	Engine_Cmpt	563823	male	C12	Engine_Cmpt	562583	female
B97	Engine_Cmpt	563816	male	C13_plug	RH_Console	563589	male
B98	Engine_Cmpt	563817	male	C13_socket	RH_Console	563590	female
B115A	Enginectpt.	564226	male	C13S	RH_Console	563589	male
B142C	Enginectpt.	563793	male	C13S	RH_Console	563590	female
B310	Enginectpt.	565967	male	C15A	Evapotatorcmpt.	568110	male
C1	FJB	563589	male	C15A	Evaporatocmpt.	568109	female
C1	FJB	563590	female	C16	RJB	561577	male
C1S	FJB	563589	male	C16	RJB	561605	female
C1S	FJB	563590	female	C17	RJB	560195	male
C2	Service_Cmpt	563580	male	C17	RJB	560169	female
C2	Service_Cmpt	563581	female	C18	FJB	561986	male
C2A	FJB	563580	male	C18	FJB	561987	female
C2A	FJB	563581	female	C19	RJB	561986	male
C2B	FJB	564034	male	C19	RJB	561987	female
C2B	FJB	564035	female	C20A	Evap_Cmpt	562485	male
C3_plug	RJB	563589	male	C20A	Evap_Cmpt	562486	female
C3_socke	RJB	563590	female	C20B	Evap_Cmpt	562485	male
C3AP	FJB	563589	male	C20B	Evap_Cmpt	562486	female
C3AP	FJB	563590	female	C23	Evaporatorcmpt.	564034	male
C3AS	FJB	563589	male	C23	Evaporatorcmpt.	564035	female
C3AS	FJB	563590	female	C24_plug	Evap_Cmpt	561690	male
C3S	RJB	563593	male	C24_socket	Evap_Cmpt	561566	female
C3S	RJB	563590	female	C25	Parcel_Rack_LH	561550	male
C4	FJB	563580	male	C25	Parcel_Rack_LH	561667	female
C4	FJB	563581	female	C25A	Parcel_Rack_RH	561669	male
C5	FJB	563589	male	C25A	Parcel_Rack_RH	561670	female
C5	FJB	563590	female	C26	Ureacmpt.	563226	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C26	Ureacmpt.	563613	female	C42	FJB	561668	male
C26A	Ureacmpt.	568110	male	C42	FJB	561551	female
C26A	Ureacmpt.	568109	female	C44_plug	FJB	561577	male
C26B	Ureacmpt.	563227	male	C44_socket	FJB	561605	female
C26B	Ureacmpt.	563614	female	C45	FJB	561643	male
C29	4rd_Lugg_Cmpt	563651	male	C45	FJB	561642	female
C29	3rd_Lugg_Cmpt	563652	female	C46	WCLCmpt.	564228	male
C30	3rd_Lugg_Cmpt	561710	male	C46	WCLCmpt.	564229	female
C30	3rd_Lugg_Cmpt	561709	female	C47	FJB	565207	male
C31S	Parcelrack	561515	male	C48	Unican	565208	male
C31S	Parcelrack	561552	female	C49	FJB	562005	male
C31W	WCL_Parcel_Rack	563227	male	C49	FJB	561714	female
C31W	WCL_Parcel_Rack	563614	female	C50	RJB	563226	male
C32	lavatory	561734	male	C50	RJB	563613	female
C32	Lavatory	561735	female	C51	Enginecmpt.	564034	male
C32L	Lavatory	562006	male	C51	Enginecmpt.	560034	female
C32L	Lavatory	560908	female	C52	Evaporatorcmpt.	563618	male
C32W	WCLcmpt.	561640	male	C52	Evaporatorcmpt.	563616	female
C32W	WCLcmpt.	561639	female	C54	Enginecmpt.	563226	male
C32X	Lavatory	561247	male	C54	Enginecmpt.	563613	female
C32X	Lavatory	561248	female	C54A	Ureacmpt.	568110	male
C33	WCLcmpt.	564034	male	C54A	Ureacmpt.	568109	female
C33	WCLcmpt.	564035	female	C54B	Enginecmpt.	563589	male
C34	RH_Console	561986	male	C54B	Enginecmpt.	563590	female
C34	RH_Console	561987	female	C55	Evap_Cmpt	561577	male
C35	lavatory	561734	male	C55	Evap_Cmpt	561605	female
C35	Lavatory	561735	female	C58	Condensorcmt.	564567	male
C36	FJB	561986	male	C58	Condensorcmt.	564568	female
C36	FJB	561987	female	C59	RJB	561643	male
C37	Parcel_Rack_LH	562557	male	C59	RJB	561642	female
C37	Parcel_Rack_LH	562558	female	C61	Fr_Service_Door	561669	male
C37.	Parcel_Rack	561734	male	C61	Fr_Service_Door	561670	female
C37.	Parcel_Rack	561735	female	C62	Fr_Service_Door	562566	male
C38	Parcelrack	562555	male	C62	Fr_Service_Door	562565	female
C38	Parcelrack	562556	female	C63	Entrance_Door	562477	male
C38.	Parcelrack	561734	male	C63	Entrance_Door	562479	female
C38.	Parcelrack	561735	female	C64	Enginecmpt.	568110	male
C39A	Firesuppressioncmpt.	561782	male	C64	Enginecmpt.	568109	female
C39A	Firesuppressioncmpt.	561781	female	C66_plug	Evap_Cmpt	561577	male
C40	Dash	562485	male	C66_socket	Evap_Cmpt	561605	female
C40	Dash	562486	female	C68_plug	Parcel_Rack_LH	562503	male
C41	RJB	561782	male	C68_socket	Parcel_Rack_LH	562507	female
C41	RJB	561781	female	C69_plug	Parcel_Rack_LH	561690	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C69_socket	Parcel_Rack_LH	561566	female	C87	Engine_Cmpt	562485	male
C55	Evap_Cmpt	561577	male	C87	Engine_Cmpt	562486	female
C55	Evap_Cmpt	561605	female	C88	FJB	563618	male
C58	Condensorcmpt.	564567	male	C88	FJB	563616	female
C58	Condensorcmpt.	564568	female	C91	RJB	564619	male
C59	RJB	561643	male	C91	RJB	562282	female
C59	RJB	561642	female	C92A	Enginecmpt.	563226	male
C61	Fr_Service_Door	561669	male	C92A	Enginecmpt.	563613	female
C61	Fr_Service_Door	561670	female	C92C	Enginecmpt.	562581	male
C62	Fr_Service_Door	562566	male	C92C	Enginecmpt.	562583	female
C62	Fr_Service_Door	562565	female	C94_plug	FJB	563589	male
C63	Entrance_Door	562477	male	C94_socket	FJB	563590	female
C63	Entrance_Door	562479	female	C96	FJB	561643	male
C64	Enginecmpt.	568110	male	C96	FJB	561642	female
C64	Enginecmpt.	568109	female	C97	FJB	561643	male
C66_plug	Evap_Cmpt	561577	male	C97	FJB	561642	female
C66_socket	Evap_Cmpt	561605	female	C100	Evaporatorcmpt.	562477	male
C68_plug	Parcel_Rack_LH	562503	male	C100	Evaporatorcmpt.	562479	female
C68_socket	Parcel_Rack_LH	562507	female	C100S	EvaporatorCmpt.	562477	male
C69_plug	Parcel_Rack_LH	561690	male	C100S	EvaporatorCmpt.	562479	female
C69_socket	Parcel_Rack_LH	561566	female	C101	Service_Cmpt	561690	male
C70	FJB	561550	male	C101	Service_Cmpt	561566	female
C70	FJB	561667	female	C102A	Condensorcmpt.	563226	male
C71	FJB	561646	male	C102A	Condensorcmpt.	563613	female
C71	FJB	561645	female	C103_plug	FJB	562485	male
C72	FJB	561646	male	C103_socket	FJB	562486	female
C72	FJB	561645	female	C105_plug	FJB	562581	male
C74	FJB	561645	female	C105_socket	FJB	562583	female
C74	FJB	561646	male	C106_plug	FJB	562581	male
C81	1st_Lugg_Cmpt	562477	male	C106_socket	FJB	562583	female
C81	1st_Lugg_Cmpt	562479	female	C107A	Enginecmpt.	562885	female
C82	1st_Lugg_Cmpt	562477	male	C107A	Enginecmpt.	562884	female
C82	1st_Lugg_Cmpt	562479	female	C107B	Enginecmpt.	562885	female
C82A	1st_Lugg_Cmpt	563589	male	C107B	Enginecmpt.	562884	female
C82A	1st_Lugg_Cmpt	563590	female	C107C	Enginecmpt.	562885	female
C83	2nd_Lugg_Cmpt	562477	male	C107C	Enginecmpt.	562884	female
C83	2nd_Lugg_Cmpt	562479	female	C110	Dash	568110	male
C84	2nd_Lugg_Cmpt	562477	male	C110	Dash	568109	female
C84	2nd_Lugg_Cmpt	562479	female	C119A	Rearenginedoor	568110	male
C85	4thlugg.cmpt.	562477	male	C119A	Rearenginedoor	568109	female
C85	4thlugg.cmpt.	562479	female	C121	Rearenginedoor	562566	male
C86	4thlugg.cmpt.	563618	male	C121	Rearenginedoor	562565	female
C86	4thlugg.cmpt.	563616	female	C122	Rearenginedoor	562566	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C122	Rearenginedoor	562565	female	C225	FJB	562650	male
C131A	Engine_Cmpt	561782	male	C225	FJB	562649	female
C131A	Engine_Cmpt	561781	female	C226	FJB	562650	male
C131B	Engine_Cmpt	561782	male	C226	FJB	562649	female
C131B	Engine_Cmpt	561781	female	C242	Service_Cmpt	562789	male
C140	Dash	562477	male	C242	Service_Cmpt	565131	female
C140	Dash	562479	female	C243	FrontVehicle	563347	male
C144	RJB	560852	male	C243	FrontVehicle	563180	female
C144	RJB	560851	female	C243.	FrontVehicle	562789	male
C152	Cond_Cmpt	561611	male	C243.	FrontVehicle	565131	female
C152	Cond_Cmpt	561610	female	C259	3rd_LH_Lugg_Cmpt	561637	male
C158	Condensorcmt.	562477	male	C259	3rd_LH_Lugg_Cmpt	561636	female
C158	Condensorcmt.	562479	female	C266	Parcelrack	561782	male
C170	LH_Console	561637	male	C266	Parcelrack	561781	female
C170	LH_Console	561636	female	C267	Parcelrack	561782	male
C171	LH_Console	561646	male	C267	Parcelrack	561781	female
C171	LH_Console	561645	female	C279	Service_Cmpt	562477	male
C187	RJB	561577	male	C279	Service_Cmpt	562479	female
C187	RJB	561605	female	C284	Parcelrack	561247	male
C188	Evap_Cmpt	561577	male	C284	Parcelrack	561248	female
C188	Evap_Cmpt	561605	female	C284_1	Parcelrack	561247	male
C189	RJB	561986	male	C284_1	Parcelrack	561248	female
C189	RJB	561987	female	C284_2	Parcelrack	561247	male
C193_plu	RJB	563589	male	C284_2	Parcelrack	561248	female
C193_so	RJB	563590	female	C284_3	Parcelrack	561247	male
C194	FJB	563589	male	C284_3	Parcelrack	561248	female
C194	FJB	563590	female	C284_4	Parcelrack	561247	male
C195	Dash	563347	male	C284_4	Parcelrack	561248	female
C195	Dash	560489	female	C284_5	Parcelrack	561247	male
C206	Parcel_Rack_RH	562503	male	C284_5	Parcelrack	561248	female
C206	Parcel_Rack_RH	562507	female	C290	Rear_Vehicle	562477	male
C207	Parcel_Rack_LH	562503	male	C290	Rear_Vehicle	562479	female
C207	Parcel_Rack_LH	562507	female	C298	Parcelrack	561782	male
C212	WCLArea	561515	male	C298	Parcelrack	561781	female
C212	WCLArea	561552	female	C355	RJB	563582	male
C213	Parcel_Rack_LH	561515	male	C355	RJB	563583	female
C213	Parcel_Rack_LH	561552	female	C356	Parcelrack	561710	male
C222	FJB	562477	male	C356	Parcelrack	561709	female
C222	FJB	562479	female	C357	Parcelrack	561847	male
C223	FJB	563227	male	C357	Parcelrack	561862	female
C223	FJB	563614	female	C380A	Dash	564222	male
C224	FJB	561637	male	C380A	Dash	564224	female
C224	FJB	561636	female	C381	Parcel_Rack	561847	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C381	Parcel_Rack	561862	female	C506spB	FJB	561687	male
C382	Under_Seat	561580	male	C506spB	FJB	561685	female
C382	Under_Seat	561582	female	C542	Parcelrack	561550	male
C397	RJB	562285	male	C542	Parcelrack	561667	female
C397	RJB	562282	female	C558	Parcelrack	562503	male
C430	LH_Console	562363	male	C558	Parcelrack	562507	female
C430	LH_Console	561188	female	C564	Parcelrack	562503	male
C452	Dash	561669	male	C564	Parcelrack	562507	female
C452	Dash	561670	female	C564-Sp	Parcelrack	562503	male
C298	Parcelrack	561782	male	C564-Sp	Parcelrack	562507	female
C298	Parcelrack	561781	female	C566	Parcelrack	562503	male
C355	RJB	563582	male	C566	Parcelrack	562507	female
C355	RJB	563583	female	C567	Parcelrack	562503	male
C356	Parcelrack	561710	male	C567	Parcelrack	562507	female
C356	Parcelrack	561709	female	C575	Parcel_Rack_RH	562503	male
C357	Parcelrack	561847	male	C575	Parcel_Rack_RH	562507	female
C357	Parcelrack	561862	female	C576B	Parcel_Rack_RH	562006	male
C380A	Dash	564222	male	C576B	Parcel_Rack_RH	560908	female
C380A	Dash	564224	female	C576BB	Parcelrack	562006	male
C381	Parcel_Rack	561847	male	C576BB	Parcelrack	560908	female
C381	Parcel_Rack	561862	female	C577A	Parcel_Rack	562006	male
C382	Under_Seat	561580	male	C577A	Parcel_Rack	560908	female
C382	Under_Seat	561582	female	C577AA	Parcelrack	562006	male
C397	RJB	562285	male	C577AA	Parcelrack	560908	female
C397	RJB	562282	female	C578	Parcel_Rack_LH	562503	male
C430	LH_Console	562363	male	C578	Parcel_Rack_LH	562507	female
C430	LH_Console	561188	female	C582	FJB	561690	female
C452	Dash	561669	male	C582	FJB	561566	female
C452	Dash	561670	female	C600	Dash	563226	male
C463	Rearaxlecmpt.	568111	male	C600	Dash	563613	female
C463	Rearaxlecmpt.	568112	female	C601	LHRoofWinAjar	561476	male
C464	FJB	564222	male	C601	LHRoofWinAjar	561477	female
C464	FJB	564224	female	C602	Parcel_Rack_LH	561668	male
C464A	Dash	564222	male	C602	Parcel_Rack_LH	561551	female
C464A	Dash	564224	female	C603	RHRoofWinAjar	561476	male
C464B	FJB	564222	male	C603	RHRoofWinAjar	561477	female
C464B	FJB	564224	female	C608	Parcel_Rack_LH	561577	male
C465	Parcelrack	562581	male	C608	Parcel_Rack_LH	561605	female
C465	Parcelrack	562583	female	C609	Parcel_Rack_LH	561550	male
C506	FJB	561687	male	C609	Parcel_Rack_LH	561667	female
C506	FJB	561685	female	C612	Parcel_Rack_LH	561687	male
C506spA	FJB	561687	male	C612	Parcel_Rack_LH	561685	female
C506spA	FJB	561685	female	C614	Passenger_Area	563071	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C614	Passenger_Area	563040	female	C_Se51	FJB	563589	male
C615	Passenger_Area	563071	male	C_Se51	FJB	563590	female
C615	Passenger_Area	563040	female	C_USB	Parcelrack	562069	male
C617	Mirror_LH	563801	male	C_USB	Parcelrack	562070	female
C617	Mirror_LH	563800	female	CCAN1	FJB	562650	male
C618	Mirror_RH	563801	male	CCAN1	FJB	562649	female
C618	Mirror_RH	563800	female	CCAN2	FJB	562650	male
C620	FJB	562477	male	CCAN2	FJB	562649	female
C620	FJB	562479	female	CCAN3	FJB	562650	male
C662_plug	FJB	562477	male	CCAN3	FJB	562649	female
C662_socket	FJB	562479	female	CCAN4	FJB	562650	male
C700	FJB	561637	male	CCAN4	FJB	562649	female
C700	FJB	561636	female	CCust	Parcel_Rack_Fr_WCL	562477	male
C700A_plug	FJB	561637	male	CCust	RJB	562479	female
C700A_socket	FJB	561636	female	CFHPR1	Parcelrack	564560	male
C752	Parcelrack	901283	female	CIND-1.A	Parcelrack	560908	female
C753	Parcelrack	901283	female	CIND-1.B	Parcelrack	560908	female
C766	Parcelrack	561662	male	CIND-2.A	Parcelrack	560908	female
C766	Parcelrack	561661	female	CIND-2.B	Parcelrack	560908	female
C768	Parcelrack	901283	female	CIND-11.A	Parcelrack	560908	female
C769	Parcelrack	901283	female	CIND-11.B	Parcelrack	560908	female
C777	Dash	562477	male	CINDWC-1.A	Parcelrack	560908	female
C777	Dash	562479	female	CINDWC-1.B	Parcelrack	560908	female
C_A60DB	Parcelrack	563071	male	CL1	Service_Cmpt	562485	male
C_A60DB	Parcelrack	563040	female	CL1	Service_Cmpt	562486	female
C_ALT	Enginecmpt.	562581	male	CL142	Lavatory	562006	male
C_ALT	Enginecmpt.	562583	female	CL142	Lavatory	560908	female
C_ALT3	Enginecmpt.	562477	male	CL142A	Lavatory	562006	male
C_ALT3	Enginecmpt.	562479	female	CL142A	Lavatory	560908	female
C_AUDIO_AUX	Parcelrack	562557	male	CP1	Passenger_Area	561782	male
C_AUDIO_AUX	Parcelrack	562558	female	CP1	Passenger_Area	561781	female
C_AUX	Parcelrack	563071	male	CP2	Passenger_Area	561782	male
C_AUX	Parcelrack	563040	female	CP2	Passenger_Area	561781	female
C_INV1	Parcelrack	562337	male	CP3	Passengersarea	561782	male
C_INV1	Parcelrack	562338	male	CP3	Passengersarea	561781	female
C_INV2	Parcelrack	562337	male	CP4	Passenger_Area	561782	male
C_INV2	Parcelrack	562338	male	CP4	Passenger_Area	561781	female
C_LineOut	Parcelrack	563962	male	CP5	Passenger_Area	561782	male
C_LineOut	Parcelrack	564489	female	CP5	Passenger_Area	561781	female
C_Mo9	Evap_Cmpt	561577	male	CP6	Passengersarea	562337	male
C_Mo9	Evap_Cmpt	561605	female	CP6	Passengersarea	562338	male
C_Mo9:2	Evap_Cmpt	561577	male	CR72	RearSeat	563409	male
C_Mo9:2	Evap_Cmpt	561605	female	CR72	RearSeat	563410	female



# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
CSe80	RJB	562477	male	L24	Frontcap	562486	female
CSe80	RJB	562479	female	L25	Frontcap	562486	female
CSw102	EngineCmpt.	562549	male	L26	Frontcap	562486	female
CSw102	EngineCmpt.	562550	female	L27	Frontcap	562486	female
CSX1	Engine_Cmpt	563135	male	L28	Parcelrack	560898	male
CSX1	Engine_Cmpt	563134	female	L29	Parcelrack	560898	male
CSX3	Engine_Cmpt	563135	male	L30	Parcelrack	560898	male
CSX3	Engine_Cmpt	563134	female	L30A.A	Parcelrack	560898	male
CP4	Passenger_Area	561782	male	L30B.A	Parcelrack	560898	male
CP4	Passenger_Area	561781	female	L31	Parcelrack	560898	male
CP5	Passenger_Area	561782	male	L32	Parcelrack	560898	male
CP5	Passenger_Area	561781	female	L33	Parcelrack	560898	male
CP5A		561782	male	L34	Parcelrack	560898	male
CP5A		561781	female	L35	Parcelrack	560898	male
CP6	Passengersarea	562337	male	L36	Parcelrack	560898	male
CP6	Passengersarea	562338	male	L37	Parcelrack	560898	male
CR72	RearSeat	563409	male	L38	Parcelrack	560898	male
CR72	RearSeat	563410	female	L39	Parcelrack	560898	male
CSe80	RJB	562477	male	L40	Parcelrack	560898	male
CSe80	RJB	562479	female	L41	Parcelrack	560898	male
CSw102	EngineCmpt.	562549	male	L42	Parcelrack	560898	male
CSw102	EngineCmpt.	562550	female	L43	Parcelrack	560898	male
CSX1	Engine_Cmpt	563135	male	L44	Parcelrack	560898	male
CSX1	Engine_Cmpt	563134	female	L45	Parcelrack	560898	male
CSX3	Engine_Cmpt	563135	male	L46	Parcelrack	560898	male
CSX3	Engine_Cmpt	563134	female	L47	Parcelrack	560898	male
CT_IN	Engine_Cmpt	563582	male	L48	Parcelrack	560898	male
CT_IN	Engine_Cmpt	563583	female	L49	Parcelrack	560898	male
CT_IN1	Engine_Cmpt	560167	male	L50	Parcelrack	560898	male
CT_IN1	Engine_Cmpt	560159	female	L51	Parcelrack	560898	male
CT_Out	Engine_Cmpt	560478	female	L52	Parcelrack	560898	male
CXC1	Service_Cmpt	562477	male	L52	Parcelrack	560900	female
CXC1	Service_Cmpt	562479	female	L52A	Parcelrack	560898	male
D92	Parcelrack	564496	male	L53	Parcelrack	560898	male
EI	Enginecmpt.	563739	male	L53	Parcelrack	560900	female
L1A	Engine_Cmpt	560774	male	L53A	Parcelrack	560898	male
L16.A	Frontroof	562615	female	L54	Parcelrack	560898	male
L16.B	Frontroof	562615	female	L54	Parcelrack	560900	female
L17.A	Frontroof	562615	female	L54A	Parcelrack	560898	male
L17.B	Frontroof	562615	female	L55	Parcelrack	560898	male
L21	Frontcap	562486	female	L55	Parcelrack	560900	female
L22	Frontcap	562486	female	L55A	Parcelrack	560898	male
L23	Frontcap	562486	female	L56	Parcelrack	560898	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
L56	Parcelrack	560900	female	L149	Parcelrack	561186	male
L56A	Parcelrack	560898	male	L150	Parcelrack	561186	male
L57	Parcelrack	560898	male	L151	Parcelrack	561186	male
L57	Parcelrack	560900	female	L152	Parcelrack	561186	male
L57A	Parcelrack	560898	male	L153	Parcelrack	561186	male
L58	Parcelrack	560898	male	L154	Parcelrack	561186	male
L58	Parcelrack	560900	female	L155	Parcelrack	561186	male
L58A	Parcelrack	560898	male	L156	Parcelrack	561186	male
L59	Out_Side_Front_RH	562623	male	L157	Parcelrack	561186	male
L59A	OutsideFrontRH	563366	male	L158	Parcelrack	561186	male
L59B	Out_Side_Front_RH	562623	male	L170	Lugg_cmpt	561690	male
L60	OutsideFrontLH	562623	male	L173.A	Parcelrack	563590	female
L60A	OutsideFrontLH	563366	male	L174A	Parcelrack	563590	female
L60B	Out_Side_Front_LH	562623	male	L176	3rd_Lugg_Cmpt	561247	male
L61	Out_Side_Front_RH	562601	male	L177	3rd_Lugg_Cmpt	561247	male
L62	Out_Side_Front_LH	562601	male	L177A	WCLCmpt.	561690	male
L71A	Rearenginedoor	562601	male	L177B	WCLCmpt.	561690	male
L73A	Rearenginedoor	562601	male	L180	2nd_Lugg_Cmpt	561247	male
L77A	Rearvehicule	562601	male	L181	2nd_Lugg_Cmpt	561247	male
L78A	Rearvehicule	562601	male	L182	1st_Lugg_Cmpt	561247	male
L79A	Rearvehicule	562601	male	L183	1st_Lugg_Cmpt	561247	male
L80A	Rearvehicule	562601	male	L184	Servicecmpt.	561247	male
L81.A	Rear_Vehicle	562835	female	L185.A	Servicecmpt.	561539	male
L81.B	Rear_Vehicle	562834	male	L185.B	Servicecmpt.	561539	male
L82A	Rearvehicule	562348	female	L186.A	Dash	561539	male
L83A	Rearvehicule	562348	female	L186.B	Dash	561539	male
L91A	Rearvehicule	562601	male	L187	Engine_Cmpt	561690	male
L92A	Rearvehicule	562601	male	L188	Service_Cmpt	562486	female
L95	Outside_Front_LH	562902	female	L193.A	Dash	560488	female
L96	Outside_Front_RH	562902	female	L193.B	Dash	560488	female
L97.A	Outside_Front_LH	563069	female	L194.A	Dash	562019	female
L97.B	Outside_Front_LH	563069	female	L194.B	Dash	560488	female
L98.A	Entrance_Door	563069	female	L195.A	Dash	560488	female
L98.B	Outside_Front_RH	563069	female	L195.B	Dash	560488	female
L140	Lavatory	561247	male	L199	Enginecmpt.	562848	male
L142	Lavatory	562006	male	L203	RH_Console	561690	male
L142B	Lavatory	562006	male	L204	Parcel_Rack_RH	562803	male
L143	Parcelrack	561186	male	L205	Enginecmpt.	562485	male
L144	Parcelrack	561186	male	L206	Parcel_Rack_RH	562803	male
L145	Parcelrack	561186	male	L207.A	WCLCmpt.	561699	female
L146	Parcelrack	561186	male	L207.B	WCLCmpt.	561701	female
L147	Parcelrack	561186	male	L207.C	WCLCmpt.	561701	female
L148	Parcelrack	561186	male	L207.D	WCLCmpt.	561699	female

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
L207.E	WCLCmpt.	561701	female	Mo10	ParcelRack_Lh_Fan	561515	male
L207.F	WCLCmpt.	561699	female	Mo11	ParcelRack_Rh_Fan	561515	male
L207.G	WCLCmpt.	561699	female	Mo12	Engine_Cmpt	561690	male
L207.H	WCLCmpt.	563536	female	Mo13	Engine_Cmpt	561690	female
L207.I	WCLCmpt.	563536	female	Mo5	Front_Roof	561515	male
L207.I	WCLCmpt.	563536	female	Mo7	Cond_Cmpt	563691	male
L243	Parcelrack	561186	male	Mo8	Cond_Cmpt	563691	male
L244	Parcelrack	561186	male	Mo10	ParcelRack_Lh_Fan	561515	male
L245	Parcelrack	561186	male	Mo11	ParcelRack_Rh_Fan	561515	male
L246	Parcelrack	561186	male	Mo12	Engine_Cmpt	561690	male
L247	Parcelrack	561186	male	Mo13	Engine_Cmpt	561690	female
L248	Parcelrack	561186	male	Mo14	Engine_Cmpt	561566	female
L249	Parcelrack	561186	male	Mo15	Front_Ceiling	560900	female
L250	Parcelrack	561186	male	Mo16	Front_Ceiling	560900	female
L251	Parcelrack	561186	male	Mo17	RH_Console	563626	male
L252	Parcelrack	561186	male	Mo19	Fr_Service_Door	562474	male
L253	Parcelrack	561186	male	Mo20	Fr_Service_Door	562474	male
L254	Parcelrack	561186	male	Mo22	RH_Console	561186	male
L255	Parcelrack	561186	male	Mo24	RH_Console	562348	female
L256	Parcelrack	561186	male	Mo25	RH_Console	562348	female
L257	Parcelrack	561186	male	Mo27	Cond_Cmpt	563691	male
L258	Parcelrack	561186	male	Mo28	Cond_Cmpt	563691	male
L282	Engine_Cmpt	561690	male	Mo29	RJBcmpt.	563590	female
L283	Service_Cmpt	562485	male	Mo30	Compr_Door	564161	male
L285.A	Rear_Vehicle	562835	female	Mo31	Parcelrack	564161	male
L285.B	Rear_Vehicle	562834	male	Mo32	Parcelrack	564161	male
L286.A	Rear_Vehicle	562835	female	Mo33	Parcelrack	564161	male
L286.B	Rear_Vehicle	562834	male	Mo34	Parcelrack	564161	male
L296	Refrigerator	561248	female	Mo35	3rd_Lugg_Door	564161	male
L298A	Enginecmpt.	563590	female	Mo36	Parcelrack	564161	male
L306	RJBcmpt.	561247	male	Mo54	Service_Cmpt	562474	male
L313	Rr_Roof	562549	male	Mo62	FrontHatch	562486	female
L350A.A	Rearaxlecmpt.	564552	male	Mo63	RearHatch	562486	female
L350A.B	Rearaxlecmpt.	563340	male	Mo65	Enginecmpt.	568089	male
L350A.C	Rearaxlecmpt.	562251	male	Mo67	Enginecmpt.	568089	male
L606	Rr_Roof	560898	male	Mo68	Enginecmpt.	568089	male
L606	Rr_Roof	560900	female	Mo69	Enginecmpt.	568089	male
L606A	Rr_Roof	560898	male	Mo70	Enginecmpt.	568089	male
Mo3	Dash	561667	female	Mo71	Enginecmpt.	568089	male
Mo4	Dash	562076	male	Mo72	Enginecmpt.	568089	male
Mo5	Front_Roof	561515	male	Mo73	Enginecmpt.	568089	male
Mo7	Cond_Cmpt	563691	male	P_In1	Passenger_Area	561782	male
Mo8	Cond_Cmpt	563691	male	P_In1	Passenger_Area	561781	female

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
P_Out1	Passenger_Area	561782	male	RadioVolvo3_966.B	Parcelrack	563962	male
P_Out1	Passenger_Area	561781	female	RadioVolvo3_966.C1	Parcelrack	563956	male
P_Out2	Passenger_Area	561782	male	RadioVolvo3_966.C2	Parcelrack	563957	male
P_Out2	Passenger_Area	561781	female	RadioVolvo3_966.C3	Parcelrack	563958	male
P_Out3	Passenger_Area	561782	male	Res3.A	RJB	563590	female
P_Out3	Passenger_Area	561781	female	Res4	FJB	563590	female
PC1	FJB	562650	male	Res6	FJB	563590	female
PC1	FJB	562649	female	Res6A	FJB	563589	male
PF	FJB	561782	male	Res6A	FJB	563590	female
PF	FJB	561781	female	Res6B	FJB	563589	male
PF1	Passenger_Area	561782	male	Res6B	FJB	563590	female
PF1	Passenger_Area	561781	female	Res7	dash	563590	female
Pot1.A	Dash	560488	female	Res15	Engine_Cmpt	561782	male
Pot1.B	Dash	560488	female	Res31	Ureacmpt.	562350	male
Pot1.C	Dash	560488	female	Res32	Ureacmpt.	563764	female
PR	Parcelrack	561782	male	Res53.A	FJB	563590	female
PR	Parcelrack	561781	female	Res99	FJB	563590	female
PR1	Passenger_Area	561782	male	Se2	LH_Console	561566	female
PR1	Passenger_Area	561781	female	Se4	Window_RH	561477	female
R3	RJB	563409	male	Se5	Window_RH	561477	female
R4	FJB	564496	male	Se6	Window_RH	561477	female
R5	RJB	564496	male	Se7	Window_LH	561477	female
R12	Evap_Cmpt	563409	male	Se8	Window_LH	561477	female
R20	RJB	564496	male	Se9	Window_LH	561477	female
R21	FJB	560525	male	Se10	FJB	561477	female
R21A	FJB	560525	male	Se11.A	Cond_Cmpt	560082	female
R26	Evap_Cmpt	564496	male	Se11.B	Cond_Cmpt	560082	female
R27	Dash	564496	male	Se11.C	Cond_Cmpt	560082	female
R28	RearSeat	563409	male	Se13	Engine_Cmpt	562350	male
R29	RJB	563409	male	Se14.A	Driver_Area	561782	male
R30	FJB	564496	male	Se14.B	Driver_Area	561781	female
R31	FJB	564496	male	Se15	RH_Console	560898	male
R34	RJB	564210	male	Se17	RH_Console	560900	female
R36	Dash	564496	male	Se18	Servicecmpt.	561566	female
R37	Dash	564496	male	Se19_P	Service_Cmpt	563677	male
R38	FJB	564496	male	Se19_S	Service_Cmpt	563677	male
R38A	RearSeat	563409	male	Se20	Evap_Cmpt	562426	male
R40	RJB	564496	male	Se20A	Evap_Cmpt	562426	male
R47	Parcelrack	564496	male	Se21	Dash	561248	female
R72.A	RearSeat	563409	male	Se23	Engine_Cmpt	563159	male
R210	Parcel_Rack_LH	560525	male	Se24	EvaporatorCmpt.	563758	female
R_12VISS	Parcelrack	564496	male	Se25	Passenger_Area	561248	female
RadioVolv	Parcelrack	563960	male	Se29	Engine_Cmpt	561566	female

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
Se30	Enginedoor	562877	female	Se79	Front_Axle	563340	male
Se31	Enginedoor	562877	female	Se80	Rear_Axle	563159	female
Se32	Rear_Axle_Cmpt	562426	male	Se89	Enginectmpt.	562350	male
Se33	Rear_Axle_Cmpt	562856	male	Se94	WCLUpperDoor	562877	female
Se34	Rear_Axle_Cmpt	562426	male	Se100	WCLdoor	562479	female
Se35	Rear_Axle_Cmpt	562426	male	shell1_1640	Driver_Area	562471	male
Se36	Rear_Axle_Cmpt	562427	male	So3	RH_Console	641385	male
Se37	Front_Axle_LH	641132	female	So4	RH_Console	641385	male
Se38	Front_Axle_RH	641132	female	So5	RH_Console	641385	male
Se39	Rear_Axle_LH	641132	female	So6	RH_Console	641385	male
Se40	Rear_Axle_LH	641132	female	So7	Service_Cmpt	561566	female
Se45	Servicecmpt.	563409	male	So8	Servicecmpt.	641385	male
Se46	Rearaxlecmpt.	562348	female	So9	Enginectmpt.	560016	female
Se49	Engine_Cmpt	561690	male	So10.A	Condensorcmpt.	562485	male
Se51	UnderDriverSeat	563589	male	So11	Cond_Cmpt	561566	female
Se53	Service_Cmpt	563159	female	So13	Evap_Cmpt	563204	female
Se54	Service_Cmpt	563159	female	So14	Servicecmpt.	641385	male
Se55	Service_Cmpt	563159	female	So15	Servicecmpt.	641385	male
Se56	WCLCmpt.	562479	female	So16	Servicecmpt.	641385	male
Se60	Service_Cmpt	563409	male	So17	Servicecmpt.	562848	male
Se62	WCL_System	561690	male	So20	Servicecmpt.	641385	male
Se63	Rearaxlecmpt.	641132	female	So21	Front_Axle_Cmpt	564046	female
Se64	Rearaxlecmpt.	641132	female	So22	Front_Axle_Cmpt	564046	female
Se65	Dash	564042	female	So23	Rear_Axle_Cmpt	564046	female
Se66	FJB	564039	female	So24	Rear_Axle_Cmpt	564046	female
Se67	Frontaxlecmpt.	563159	female	So27	Rearaxlecmpt.	564045	female
Se69	Frontaxlecmpt.	563159	female	So29	Parcelrack	641385	male
Se74	Rear_Axle_Cmpt	563340	male	So50	Rearaxlecmpt.	564046	female
Se75	Service_Cmpt	563159	female	So52	Rearaxlecmpt.	564045	female
Se76	EntranceDoor	562479	female	So53	Rear_Axle_Cmpt	641385	male
Se77	FJB	563159	female	So54	Enginectmpt.	564045	female
Se78	Pneumaticplate	563159	female	So55	Pneumaticplate	562848	male
Se79	Front_Axle	563340	male	So56	Rear_Axle_Cmpt	562350	male
Se80	Rear_Axle	563159	female	So57	Engine_Cmpt	562350	male
Se89	Enginectmpt.	562350	male	spBar4	Enginectmpt.	564135	male
Se94	WCLUpperDoor	562877	female	spBar5	Enginectmpt.	564135	male
Se100	WCLdoor	562479	female	spBar6	Enginectmpt.	564135	male
Se69	Frontaxlecmpt.	563159	female	spBar7	Enginectmpt.	564135	male
Se74	Rear_Axle_Cmpt	563340	male	spBar11	Rearvehicule	564135	male
Se75	Service_Cmpt	563159	female	spBar12	Rearvehicule	564135	male
Se76	EntranceDoor	562479	female	spBar13	Enginectmpt.	564135	male
Se77	FJB	563159	female	spBar14	Enginectmpt.	564135	male
Se78	Pneumaticplate	563159	female	spBar15	Enginectmpt.	564135	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
spBar16	Enginercmpt.	564135	male	Sw1.C258	Driver_Area	561188	female
spBar19	Condensorcmt.	564135	male	Sw1.C259	Driver_Area	561186	male
spBar20	Condensorcmt.	564135	male	Sw2	Dash	562763	male
spBar21	Condensorcmt.	564135	male	Sw3	Dash	562763	male
spBar22	Enginercmpt.	564135	male	Sw4	Dash	562763	male
spBar23	Enginercmpt.	564135	male	Sw6	Dash	562763	male
spBar24	Enginercmpt.	564135	male	Sw10A	LH_Console	562763	male
Spk1_L	Parcel_Rack_LH	563994	male	Sw10A	LH_Console	562763	male
Spk1_R	Parcel_Rack_RH	563994	male	Sw14	Dash	562763	male
Spk2_L	Parcel_Rack_LH	563994	male	Sw16	Dash	562763	male
Spk2_R	Parcel_Rack_RH	563994	male	Sw17	Dash	562763	male
Spk3_L	Parcel_Rack_LH	563994	male	Sw18A	LH_Console	562763	male
Spk3_R	Parcel_Rack_RH	563994	male	Sw20	Dash	562763	male
Spk4_L	Parcel_Rack_LH	563994	male	Sw21	Dash	562763	male
Spk4_R	Parcel_Rack_RH	563994	male	Sw24	Dash	562763	male
Spk5_L	Parcel_Rack_LH	563994	male	Sw24A	Dash	562763	male
Spk5_R	Parcel_Rack_RH	563994	male	Sw25	Dash	562763	male
Spk6_L	Parcel_Rack_LH	563994	male	Sw26	Dash	562763	male
Spk6_R	Parcel_Rack_RH	563994	male	Sw27	Dash	562763	male
Spk7_L	Parcel_Rack_LH	563994	male	Sw29	Dash	562763	male
Spk7_R	Parcel_Rack_RH	563994	male	Sw30	RJB	563135	male
Spk8_L	Parcel_Rack_LH	563994	male	Sw32	Dash	561477	female
Spk8_R	Parcel_Rack_RH	563994	male	Sw33	Dash	561476	male
Spk9_L	Parcel_Rack_LH	563994	male	Sw34	Outside_Front_RH	562477	male
Spk9_R	Parcel_Rack_RH	563994	male	Sw35	Console	562763	male
Spk10_L	Parcel_Rack_LH	563994	male	Sw38	LH_Console	562763	male
Spk10_R	Parcel_Rack_RH	563994	male	Sw40	LH_Console	561690	male
Spk11_L	Parcel_Rack_LH	563994	male	Sw41	LH_Console	562749	male
Spk11_R	Parcel_Rack_RH	563994	male	Sw42	WCLCmpt.	561635	female
Spk12_L	Parcel_Rack_LH	563994	male	Sw43	LH_Console	561690	male
Spk12_R	Parcel_Rack_RH	563994	male	Sw44.A	Servicecmpt.	562403	female
Spk13_L	Parcel_Rack_LH	563994	male	Sw45.A	3rd_Lugg_Cmpt	562403	female
Spk13_R	Parcel_Rack_RH	563994	male	Sw46.A	3rd_Lugg_Cmpt	562403	female
Spk14_L	Parcel_Rack_LH	563994	male	Sw46A.A	3rdlugg.cmpt.	562403	female
Spk14_R	Parcel_Rack_RH	563994	male	Sw49.A	2nd_Lugg_Cmpt	562403	female
Spk15_L	Parcel_Rack_LH	563994	male	Sw50.A	2nd_Lugg_Cmpt	562403	female
Spk15_R	Parcel_Rack_RH	563994	male	Sw51.A	1st_Lugg_Cmpt	562403	female
Spk16_L	Parcel_Rack_LH	563994	male	Sw52.A	1st_Lugg_Cmpt	562403	female
Spk16_R	Parcel_Rack_RH	563994	male	Sw55.A	Lavatory	560488	female
SpkDr_L	Parcelrack	563994	male	Sw55.B	Lavatory	560488	female
SpkDr_R	Parcelrack	563994	male	Sw56.A	Lavatory	560488	female
Sub1.A	Passenger_Area	564004	female	Sw56.B	Lavatory	560488	female
Sub2	Passenger_Area	564004	male	Sw58	EngineCmpt.	563135	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
Sw59	Engincmpt.	563135	male	Sw115.A	Compr_Door	560079	female
Sw63A	LHConsole	562763	male	Sw115.B	Compr_Door	560079	female
Sw64.A	Service_Cmpt	560815	female	Sw125.A	Service_Cmpt	561457	female
Sw64.B	Service_Cmpt	560815	female	Sw125.B	Service_Cmpt	561457	female
Sw80A	Dash	562763	male	Sw134.A	WCLArea	562615	female
Sw82	RJB	563135	male	Sw134.B	WCLArea	562615	female
Sw83.A	Dash	560082	female	Sw134.C	WCLArea	562615	female
Sw83.B	Dash	560815	female	Sw135.A	WCLdoor	562119	female
Sw83.C	Dash	560082	female	Sw135.B	WCLdoor	562119	female
Sw83.D	Dash	560815	female	Sw135.C	WCLdoor	562119	female
Sw83A	Dash	562581	male	Sw137	Dash	562763	male
Sw85	LH_Console	562749	male	Sw140	FJB	561566	female
Sw95.A	WCLdoor	562615	female	Sw142	LHConsole	562763	male
Sw95.B	WCLdoor	562615	female	Sw149	Dash	562763	male
Sw95.C	WCLdoor	562615	female	Sw150.A	Driver_Area	560081	female
Sw96.A	WCL_Door	562615	female	Sw150.B	Driver_Area	560081	female
Sw96.B	WCL_Door	562615	female	Sw153	Dash	562763	male
Sw96.C	WCLdoor	562615	female	Sw156	LH_Console	562763	male
Sw97.A	WCLsystem	562615	female	Sw157	Dash	562763	male
Sw97.B	WCLsystem	562615	female	Sw158	Dash	562763	male
Sw97.C	WCLsystem	562615	female	Sw158	Dash	562763	male
Sw98.A	WCLsystem	562615	female	Sw313.A	Lavatory	562615	female
Sw98.B	WCLsystem	562615	female	Sw313.B	Lavatory	562615	female
Sw98.C	WCLsystem	562615	female	Sw313.C	Lavatory	562615	female
Sw100A	Dash	562763	male	VECF1	FJB	563186	male
Sw102	RJB	561566	female	VECF2	FJB	563183	male
Sw109.A	1st_Lugg_LH	560079	female	VECF3	FJB	563185	male
Sw109.B	1st_Lugg_LH	560079	female	VECF4	FJB	563182	male
Sw110.A	1st_Lugg_RH	560079	female	VECF9	FJB	563448	male
Sw110.B	1st_Lugg_RH	560079	female	VECF10	FJB	563181	male
Sw111.A	2ndlugg.cmpt.	560079	female	VECF11	FJB	563184	male
Sw111.B	2ndlugg.cmpt.	560079	female	VECF12	FJB	563187	male
Sw112.A	2ndlugg.cmpt.	560079	female	VECPR1	Parcelrack_LH	563715	male
Sw112.B	2ndlugg.cmpt.	560079	female	VECPR2_plug	Parcelrack_LH	563716	male
Sw113.A	2ndlugg.cmpt.	560079	female	VECPR3_plug	Parcelrack_LH	563718	male
Sw113.B	2ndlugg.cmpt.	560079	female	VECPR4	Parcelrack_LH	563714	male
Sw114.A	3rd_Lugg_RH	560079	female	VECPR5	Parcelrack_LH	566021	male
Sw114.B	3rd_Lugg_RH	560079	female	VECPR6	Parcelrack_LH	566020	male
Sw115.A	Compr_Door	560079	female	VECR1	RJB	563186	male
Sw115.B	Compr_Door	560079	female	VECR2	RJB	563183	male
Sw113.B	2ndlugg.cmpt.	560079	female	VECR3	RJB	563185	male
Sw114.A	3rd_Lugg_RH	560079	female	VECR4	RJB	563182	male
Sw114.B	3rd_Lugg_RH	560079	female	VECR9	RJB	563448	male

