

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
24SS_OP	Parcel_Rack_LH	563071	male	A34.J	Enginectmpt.	568118	male
24SS_OP	Parcel_Rack_LH	563040	female	A34.K	Enginectmpt.	564270	male
24SS_OP_2	Parcel_Rack_LH	563071	male	A34.L	Enginectmpt.	564269	male
24SS_OP_2	Parcel_Rack_LH	563040	female	A36.JA	FJB	562767	male
120V_inlet	Rearvehicule	561572	male	A36.JB	FJB	562765	male
A1	RJB	563975	male	A36.JC	FJB	562957	male
A2	FJB	563984	male	A39.P101	Parcel_Rack_LH	563201	male
A3	Dash	562363	male	A39.P901	Parcel_Rack_LH	563953	male
A4.A	Service_Cmpt	562428	female	A41.J1	FJB	563679	male
A4.B	Service_Cmpt	561188	female	A41.J2	FJB	564037	male
A5	Service_Cmpt	562428	female	A41.J3	FJB	564004	male
A6	Engine_Cmpt	562427	male	A60.A	Parcel_Rack_LH	563071	male
A7	Rear_Axle_Cmpt	563979	male	A60.B	Parcel_Rack_LH	562706	female
A9.Cx1	FJB	564041	female	A60.C	Parcel_Rack_LH	901110	male
A9.Cx2	FJB	563678	male	A60.D	Parcel_Rack_LH	901110	male
A9.Cx3	FJB	564037	female	A61.A	Parcel_Rack_LH	562464	male
A9.Cx4	FJB	564038	female	A61.B	Parcel_Rack_LH	562465	male
A10.X1	Engine_Cmpt	563135	male	A65.A	Parcel_Rack_LH	563025	male
A10.X3	Engine_Cmpt	563134	female	A65.B4	Parcel_Rack_LH	bidon	male
A11	LH_Console	563142	male	A65.B5	Parcel_Rack_LH	bidon	male
A14.A	Dash	562766	male	A65.B6	Parcel_Rack_LH	bidon	male
A14.B	Dash	562767	male	A65.D	Parcel_Rack_LH	bidon	male
A14.C	Dash	562765	male	A65.E	Parcelrack	563071	male
A15	Dash	562464	male	A65.G1	Parcel_Rack_LH	563071	male
A17.D	RJB	561932	male	A65.G2	Parcel_Rack_LH	563071	male
A18.J1	FJB	562794	male	A65.G3	Parcel_Rack_LH	563071	male
A18.J2	FJB	562650	male	A65.H1	Parcel_Rack_LH	561716	female
A19	LH_Console	562878	female	A65.H2	Parcel_Rack_LH	561716	female
A20	Parcel_Rack_LH	561477	female	A65.H3	Parcel_Rack_LH	561716	female
A24.A	RH_Console	561890	male	A65.J	Parcel_Rack_LH	562465	male
A24.B	RH_Console	561566	female	A69L.A	Parcel_Rack_LH	563025	male
A24.C	RH_Console	561889	female	A69L.B1	Parcel_Rack_LH	bidon	male
A25	Parcel_Rack_LH	563025	male	A69L.B2	Parcel_Rack_LH	bidon	male
A26.P1	Enginectmpt.	562350	male	A69L.B3	Parcel_Rack_LH	bidon	male
A26.P2	Enginectmpt.	563322	female	A69L.B4	Parcel_Rack_LH	bidon	male
A26.P4	Enginectmpt.	568088	male	A69L.C	Parcel_Rack_LH	bidon	male
A27	Service_Cmpt	562929	male	A69R.A	Parcel_Rack_LH	563025	male
A28	Service_Cmpt	562928	male	A69R.B1	Parcel_Rack_LH	bidon	male
A29	Dash	562464	male	A69R.B2	Parcel_Rack_LH	bidon	male
A29.	Dash	562464	male	A69R.B3	Parcel_Rack_LH	bidon	male
A29.	Dash	565871	female	A69R.B4	Parcel_Rack_LH	bidon	male
A33.A	Parcel_Rack_LH	563071	male	A69R.C	Parcel_Rack_LH	bidon	male
A33.B	Parcel_Rack_LH	562330	female	A70c	Parcel_Rack_LH	561540	female

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
A77	Parcelrack	564547	male	A120.C3	Dashboard	563958	male
A78	Parcelrack	562583	female	A121.Vsa	Dash	563679	male
A79	Parcelrack	562583	female	A121.Vsb	Dash	563678	male
A80	Parcelrack	562479	female	A121.Vsc	Dash	564037	male
A81.JA	FJB	562767	male	A121.Vsd	Dash	564118	male
A81.JB	FJB	562765	male	A130	Driver_Area	563226	male
A81.JC	FJB	562957	male	A131.A	Engine_Cmpt	561782	male
A83	Parcelrack	565970	female	A131.B	Engine_Cmpt	561781	female
A95.A	Parcelrack	564489	female	A137A	Condensercmpt.	20429843	male
A95.B	Parcelrack	562706	female	A138	Cond_Cmpt	563787	male
A95.C	Parcelrack	562706	female	A139	Dash	564501	male
A96.A	FJB	564205	male	A150	Parcelrack	21280133	male
A96S	FJB	564073	female	A152.A	Parcelrack	561550	male
A97	Dash	563226	male	A152.B	Parcelrack	563071	male
A97A	FJB	563226	male	A152.C	Parcelrack	563071	male
A97A	FJB	563613	female	A152.D	Parcelrack	563071	male
A97B	FJB	563226	male	A152.E	Parcelrack	563071	male
A97B	FJB	563613	female	A152.F	Parcelrack	563071	male
A97S.A1	Dash	564401	male	A152.G	Parcelrack	563071	male
A97S.A2	Dash	564402	male	A152.H	Parcelrack	563071	male
A97S.A3	Dash	564403	male	A152.I	Parcelrack	563071	male
A99	FJB	564205	male	A152.J	Parcelrack	563071	male
A100	Front_Axle_Cmpt	563758	female	A152.K	Parcelrack	562779	male
A100S	Front_Axle_Cmpt	563758	female	A152.L	Parcelrack	562779	male
A101	Rear_RH_Axle_Cmpt	563758	female	A162.A	FrontCab	561690	male
A101S	Rear_RH_Axle_Cmpt	563758	female	A162.B	FrontCab	561782	male
A102	Rear_RH_Axle_Cmpt	563758	female	A164.A	RH_trapezoidal_window	561690	male
A102S	Rear_RH_Axle_Cmpt	563758	female	A164.B	RH_trapezoidal_window	561782	male
A103	Dash	562070	female	A166	RearCab	561637	male
A107	EngineCmpt.	560336	male	A614.A	Parcelrack	561550	male
A108	RJB	562766	male	A614.C1	Parcelrack	563071	male
A109A	FJB	564141	male	A614.C2	Parcelrack	563071	male
A111	RJB	562550	female	A614.C3	Parcelrack	563071	male
A113.A	Parcel_Rack_LH	563960	male	A614.C4	Parcelrack	563071	male
A113.B	Parcel_Rack_LH	563962	male	A614.C5	Parcelrack	563071	male
A113.C1	Parcel_Rack_LH	563956	male	A614.C6	Parcelrack	563071	male
A113.C2	Parcel_Rack_LH	563957	male	A614.I/O	ParcelRack	bidon	male
A113.C3	Parcel_Rack_LH	563958	male	A614.P1	Parcelrack	562783	male
A114A	Dash	564252	male	A614.P2	Parcelrack	562783	male
A120.A	Dashboard	563960	male	A614.P3	Parcelrack	562783	male
A120.B	Dashboard	563962	male	AE41.J1	FJB	563679	male
A120.C1	Dashboard	563956	male	AE41.J2	FJB	564037	female
A120.C2	Dashboard	563957	male	AE41.J3	FJB	564004	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
AE42.J1	FJB	563679	male	AE53.J2	LH_ParcelRack	564037	female
AE42.J2	FJB	564037	female	AE53.J3	LH_ParcelRack	565957	male
AE42.J3	FJB	564004	male	AE54.J1	Evaporatorcmpt.	563679	male
AE43.J1	FJB	563679	male	AE54.J2	Evaporatorcmpt.	564037	female
AE43.J2	FJB	564037	male	AE54.J3	Evaporatorcmpt.	565957	male
AE43.J3	FJB	565957	male	AE55.J1	Dash	563679	male
AE44.J1	FJB	563679	male	AE55.J2	Dash	564037	female
AE44.J2	FJB	564037	female	AE55.J3	Dash	564004	male
AE44.J3	FJB	565957	male	AE56.J1	Dash	563679	male
AE45.J1	FJB	563679	male	AE56.J2	Dash	564037	male
AE45.J2	FJB	564037	female	AE56.J3	Dash	564004	male
AE45.J3	FJB	565957	male	AE57.J1	WCLcmpt.	563679	male
AE46.J1	FJB	563679	male	AE57.J2	WCLcmpt.	564037	male
AE46.J2	FJB	564037	female	AE57.J3	WCLcmpt.	564004	male
AE46.J3	FJB	565957	male	AltLL.A	Enginecmpt.	563746	female
AE47.J1	RH_console	563679	male	AltLL.B	Enginecmpt.	560815	female
AE47.J2	RH_console	564037	female	AltLL.C	Enginecmpt.	564469	female
AE47.J3	RH_console	565957	male	AltLR.A	enginecmpt.	563746	female
AE48.J1	RH_console	563679	male	AltLR.B	Enginecmpt.	560815	female
AE48.J2	RH_console	564037	female	AltLR.C	Enginecmpt.	564469	female
AE48.J3	RH_console	565957	male	AltUR.A	Enginecmpt.	563746	female
AE49..J1	RJB	563679	male	AltUR.B	Enginecmpt.	560815	female
AE49..J2	RJB	564037	male	AltUR.C	Enginecmpt.	564469	female
AE49..J3	RJB	565957	male	B85	Engine_Cmpt	563815	male
AE49.J1	RJB	563679	male	B96	Engine_Cmpt	563821	male
AE49.J2	RJB	564037	male	B96B	Engine_Cmpt	563823	male
AE49.J3	RJB	565957	male	B97	Engine_Cmpt	563816	male
AE50..J1	RJB	563679	male	B98	Engine_Cmpt	563817	male
AE50..J2	RJB	564037	male	B99	Engine_Cmpt	563815	male
AE50..J3	RJB	565957	male	B115A	Enginecmpt.	564226	male
AE50.J1	RJB	563679	male	B142C	Condensercmpt.	563793	male
AE50.J2	RJB	564037	male	B310	Enginecmpt.	565967	male
AE50.J3	RJB	565957	male	C1	FJB	563589	male
AE51.J1	RJB	563679	male	C1	FJB	563590	female
AE51.J2	RJB	564037	female	C1S	FJB	563589	male
AE51.J3	RJB	565957	male	C1S	FJB	563590	female
AE52..J1	RJB	563679	male	C2	Service_Cmpt	563580	male
AE52..J2	RJB	564037	male	C2	Service_Cmpt	563581	female
AE52..J3	RJB	565957	male	C2A	FJB	563580	male
AE52.J1	RJB	563679	male	C2A	FJB	563581	female
AE52.J2	RJB	564037	female	C2B	FJB	564034	male
AE52.J3	RJB	565957	male	C2B	FJB	564035	female
AE53.J1	LH_ParcelRack	563679	male	C3_plug	RJB	563589	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C3_socket	RJB	563590	female	C20A	Evap_Cmpt	562485	male
C3AP	FJB	563589	male	C20A	Evap_Cmpt	562486	female
C3AP	FJB	563590	female	C20B	Evap_Cmpt	562485	male
C3AS	FJB	563589	male	C20B	Evap_Cmpt	562486	female
C3AS	FJB	563590	female	C23	Evaporatorcmpt.	564034	male
C3S	RJB	563593	male	C23	Evaporatorcmpt.	564035	female
C3S	RJB	563590	female	C24_plug	Evap_Cmpt	561690	male
C4	FJB	563580	male	C24_socket	Evap_Cmpt	561566	female
C4	FJB	563581	female	C25	Parcel_Rack_LH	561550	male
C5	FJB	563589	male	C25	Parcel_Rack_LH	561667	female
C5	FJB	563590	female	C26	Ureacmpt.	563226	male
C5S	FJB	563589	male	C26	Ureacmpt.	563613	female
C5S	FJB	563590	female	C26A	Ureacmpt.	568110	male
C6	FJB	563582	male	C26A	Ureacmpt.	568109	female
C6	FJB	563583	female	C26B	Ureacmpt.	563227	male
C7	Service_Cmpt	562581	male	C26B	Ureacmpt.	563614	female
C7	Service_Cmpt	562583	female	C29	4rd_Lugg_Cmpt	563651	male
C8	FJB	563227	male	C29	3rd_Lugg_Cmpt	563652	female
C8	FJB	563614	female	C30	3rd_Lugg_Cmpt	561710	male
C9	RJB	561986	male	C30	3rd_Lugg_Cmpt	561709	female
C9	RJB	561987	female	C31W	Parcelrack	563227	male
C10	Engine_Cmpt	562581	male	C31W	Parcelrack	563614	female
C10	Engine_Cmpt	562583	female	C32	lavatory	561734	male
C11	Service_Cmpt	563580	male	C32	Lavatory	561735	female
C11	Service_Cmpt	563581	female	C32W	WCLcmpt.	561669	male
C12	Engine_Cmpt	562581	male	C32W	WCLcmpt.	561670	female
C12	Engine_Cmpt	562583	female	C33	WCLcmpt.	564034	male
C13_plug	RH_Console	563589	male	C33	WCLcmpt.	564035	female
C13_socket	RH_Console	563590	female	C34	RH_Console	561986	male
C13S	RH_Console	563589	male	C34	RH_Console	561987	female
C13S	RH_Console	563590	female	C36	FJB	561986	male
C14	WCLsystem	561550	male	C36	FJB	561987	female
C14	WCLsystem	561667	female	C37	Parcel_Rack_LH	562557	male
C15A	Evapotatorcmpt.	568110	male	C37	Parcel_Rack_LH	562558	female
C15A	Evaporatotcmpt.	568109	female	C37.	Parcel_Rack_LH	561734	male
C16	RJB	561577	male	C37.	Parcel_Rack_LH	561735	female
C16	RJB	561605	female	C38	Parcelrack	562555	male
C17	RJB	560195	male	C38	Parcelrack	562556	female
C17	RJB	560169	female	C38.	Parcelrack	561734	male
C18	FJB	561986	male	C38.	Parcelrack	561735	female
C18	FJB	561987	female	C39	Parcelrack	562503	male
C19	RJB	561986	male	C39	Parcelrack	562507	female
C19	RJB	561987	female	C39A	Firesuppressioncmpt.	561782	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C39A	Firesuppressioncmpt.	561781	female	C72	FJB	561646	male
C40	Dash	562485	male	C72	FJB	561645	female
C40	Dash	562486	female	C74	FJB	561645	female
C41	RJB	561782	male	C74	FJB	561646	male
C41	RJB	561781	female	C87	Engine_Cmpt	562485	male
C44_plug	FJB	561577	male	C87	Engine_Cmpt	562486	female
C44_socket	FJB	561605	female	C88	WCL_Cmpt.	563226	male
C45	FJB	561643	male	C88	WCL_Cmpt.	563613	female
C45	FJB	561642	female	C90	RJB	563582	male
C46	3rdlugg.cmpt.	562549	male	C90	RJB	563583	female
C46	3rdlugg.cmpt.	562550	female	C91	RJB	562285	male
C47	FJB	565207	male	C91	RJB	562282	female
C48	RJB	565208	male	C94_plug	FJB	563589	male
C49	FJB	562005	male	C94_socket	FJB	563590	female
C49	FJB	561714	female	C96	FJB	561646	male
C50	RJB	568110	male	C96	FJB	561645	female
C50	RJB	568109	female	C97	FJB	561643	male
C54	Engine_Cmpt.	563226	male	C97	FJB	561642	female
C54	Engine_Cmpt.	563613	female	C99	Enginecmpt.	562581	male
C54A	Ureacmpt.	568110	male	C99	Enginecmpt.	562583	female
C54A	Ureacmpt.	568109	female	C100	Evaporatorcmpt.	562477	male
C54B	Engine_Cmpt.	562477	male	C100	Evaporatorcmpt.	562479	female
C54B	Engine_Cmpt.	562479	female	C100S	Evaporator_Cmpt.	562477	male
C55	Evap_Cmpt	561577	male	C100S	Evaporator_Cmpt.	562479	female
C55	Evap_Cmpt	561605	female	C101	Service_Cmpt	561690	male
C59	RJB	561643	male	C101	Service_Cmpt	561566	female
C59	RJB	561642	female	C103_plug	FJB	562485	male
C63	Entrance_Door	562581	male	C103_socket	FJB	562486	female
C63	Entrance_Door	562583	female	C105_plug	FJB	562581	male
C64	Enginecmpt.	568110	male	C105_socket	FJB	562583	female
C64	Enginecmpt.	568109	female	C106_plug	FJB	562581	male
C64X	Aisle_section	560898	male	C106_socket	FJB	562583	female
C64X	Aisle_section	560900	female	C107A	Enginecmpt.	562885	female
C66_plug	Evap_Cmpt	561577	male	C107A	Enginecmpt.	562884	female
C66_socket	Evap_Cmpt	561605	female	C107B	Enginecmpt.	562885	female
C67	Parcelrack	561734	male	C107B	Enginecmpt.	562884	female
C67	Parcelrack	561735	female	C107C	Enginecmpt.	562885	female
C69_plug	FJB	561690	male	C107C	Enginecmpt.	562884	female
C69_socket	FJB	561566	female	C108	Dash	562557	male
C70	FJB	562557	male	C108	dash	562558	female
C70	FJB	562558	female	C110	Dash	568110	male
C71	FJB	561646	male	C110	Dash	568109	female
C71	FJB	561645	female	C119A	Rear_engine_door	568110	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C119A	Rear_engine_door	568109	female	C213	Parcel_Rack_LH	561515	male
C124	DashBoard	562503	male	C213	Parcel_Rack_LH	561552	female
C124	DashBoard	562507	female	C222	FJB	562477	male
C131A	Engine_Cmpt	561782	male	C222	FJB	562479	female
C131A	Engine_Cmpt	561781	female	C223	FJB	563227	male
C131B	Engine_Cmpt	561782	male	C223	FJB	563614	female
C131B	Engine_Cmpt	561781	female	C224	FJB	561637	male
C144	RJB	560852	male	C224	FJB	561636	female
C144	RJB	560851	female	C225	FJB	562650	male
C152	Cond_Cmpt	561611	male	C225	FJB	562649	female
C152	Cond_Cmpt	561610	female	C226	FJB	562650	male
C162	FrontCab	561690	male	C226	FJB	562649	female
C162	FrontCab	561566	female	C226a_plug	FJB	562650	male
C164A	RH_Trapezoidal_Window	561690	male	C226a_socket	FJB	562649	female
C164A	RH_Trapezoidal_Window	561566	female	C266	Parcelrack	561782	male
C164B	RH_Trapezoidal_Window	561782	male	C266	Parcelrack	561781	female
C164B	RH_Trapezoidal_Window	561781	female	C267	Parcelrack	561782	male
C167	FJB	561577	male	C267	Parcelrack	561781	female
C167	FJB	561605	female	C279	Service_Cmpt	562477	male
C170	LH_Console	561637	male	C279	Service_Cmpt	562479	female
C170	LH_Console	561636	female	C279A	Service_Cmpt	562477	male
C171	LH_Console	561646	male	C279A	Service_Cmpt	562479	female
C171	LH_Console	561645	female	C284	Parcel_Rack	561782	male
C175	RJB	563226	male	C284	Parcel_Rack	561781	female
C175	RJB	563613	female	C284_1	Parcel_Rack	561782	male
C175.	RJB	563226	male	C284_1	Parcel_Rack	561781	female
C175.	RJB	563613	female	C284_2	Parcel_Rack	561782	male
C187	RJB	561577	male	C284_2	Parcel_Rack	561781	female
C187	RJB	561605	female	C284_3	Parcel_Rack	561782	male
C188	Evap_Cmpt	561577	male	C284_3	Parcel_Rack	561781	female
C188	Evap_Cmpt	561605	female	C284_4	Parcel_Rack	561782	male
C189	RJB	561986	male	C284_4	Parcel_Rack	561781	female
C189	RJB	561987	female	C284_5	Parcel_Rack	561782	male
C193_plug	RJB	563589	male	C284_5	Parcel_Rack	561781	female
C193_socket	RJB	563590	female	C284_6	Parcel_Rack	561782	male
C194	FJB	563589	male	C284_6	Parcel_Rack	561781	female
C194	FJB	563590	female	C298	Parcelrack	561782	male
C195	dash	563347	male	C298	Parcelrack	561781	female
C195	dash	560489	female	C333	Upper_front	561550	male
C206	Parcel_Rack_RH	562503	male	C333	Upper_front	561667	female
C206	Parcel_Rack_RH	562507	female	C355	RJB	563582	male
C207	Parcel_Rack_LH	562503	male	C355	RJB	565887	female
C207	Parcel_Rack_LH	562507	female	C356	Parcelrack	561710	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C356	Parcelrack	561709	female	C575	Parcel_Rack_RH	562503	male
C356A	Parcelrack	561515	male	C575	Parcel_Rack_RH	562507	female
C356A	Parcelrack	561552	female	C576B	Parcel_Rack_RH	562006	male
C357	Parcelrack	561847	male	C576B	Parcel_Rack_RH	560908	female
C357	Parcelrack	561862	female	C576BB	Parcelrack	562006	male
C380A	Dash	564222	male	C576BB	Parcelrack	560908	female
C380A	Dash	564224	female	C577A	Parcel_Rack	562006	male
C381	Parcel_Rack	561847	male	C577A	Parcel_Rack	560908	female
C381	Parcel_Rack	561862	female	C577AA	Parcelrack	562006	male
C382	Under_Seat	561580	male	C577AA	Parcelrack	560908	female
C382	Under_Seat	561582	female	C578	Parcel_Rack_LH	562503	male
C397	RJB	562285	male	C578	Parcel_Rack_LH	562507	female
C397	RJB	562282	female	C582	FJB	561690	female
C397.	RJB	562285	male	C582	FJB	561566	female
C397.	RJB	562282	female	C600	Dash	563226	male
C430	LH_Console	562363	male	C600	Dash	563613	female
C430	LH_Console	561188	female	C600A	Dash	563226	male
C452	Dash	561669	male	C600A	Dash	563613	female
C452	Dash	561670	female	C600B	Dash	563226	male
C463	Rearaxlecmpt.	568111	male	C600B	Dash	563613	female
C463	Rearaxlecmpt.	568112	female	C601	LHRoofWinAjar	561476	male
C464	FJB	564222	male	C601	LHRoofWinAjar	561477	female
C464	FJB	564224	female	C602	RH_Roof_Win_Ajar	561476	male
C464A	Dash	564222	male	C602	RH_Roof_Win_Ajar	561477	female
C464A	Dash	564224	female	C603	RHRoofWinAjar	561476	male
C464B	FJB	564222	male	C603	RHRoofWinAjar	561477	female
C464B	FJB	564224	female	C614	Passenger_Area	563071	male
C465	Parcelrack	562581	male	C614	Passenger_Area	563040	female
C465	Parcelrack	562583	female	C615	Passenger_Area	563071	male
C506	FJB	561687	male	C615	Passenger_Area	563040	female
C506	FJB	561685	female	C617	Mirror_LH	563801	male
C542	Parcelrack	561550	male	C617	Mirror_LH	563800	female
C542	Parcelrack	561667	female	C618	Mirror_RH	563801	male
C558	Parcelrack	562503	male	C618	Mirror_RH	563800	female
C558	Parcelrack	562507	female	C621	Aisle_section	560898	male
C564	Parcelrack	562503	male	C621	Aisle_section	560900	female
C564	Parcelrack	562507	female	C624_plug	Rear_Galley	561690	male
C564_Sp	Parcelrack	562503	male	C624_socket	Rear_Galley	561566	female
C564_Sp	Parcelrack	562507	female	C626	FJB	562485	male
C566	Parcelrack	562503	male	C626	FJB	562486	female
C566	Parcelrack	562507	female	C629	DashBoard	561690	male
C567	Parcelrack	562503	male	C629	DashBoard	561566	female
C567	Parcelrack	562507	female	C630	Parcel_Rack	561690	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
C630	Parcel_Rack	561566	female	C_Audio_HDMI_R	Parcel_Rack	901283	female
C633	Aisle_section	560898	male	C_AUX	Parcelrack	563071	male
C633	Aisle_section	560900	female	C_AUX	Parcelrack	563040	female
C634	Aisle_section	560898	male	C_AUX_2	Parcelrack	563071	male
C634	Aisle_section	560900	female	C_AUX_2	Parcelrack	563040	female
C636	Aisle_section	560898	male	C_INV1	Parcelrack	562337	male
C636	Aisle_section	560900	female	C_INV1	Parcelrack	562338	male
C645	Aisle_section	560898	male	C_INV2	Parcelrack	562337	male
C645	Aisle_section	560900	female	C_INV2	Parcelrack	562338	male
C660	Rear_Galley	562646	male	C_LineOut	Parcelrack	563962	male
C660	Rear_Galley	562647	female	C_LineOut	Parcelrack	564489	female
C662	FJB	562477	male	C_Mo9	Evap_Cmpt	561577	male
C662	FJB	562479	female	C_Mo9	Evap_Cmpt	561605	female
C700	FJB	561637	male	C_Mo9:2	Evap_Cmpt	561577	male
C700	FJB	561636	female	C_Mo9:2	Evap_Cmpt	561605	female
C710	Front_LH_ParcelRack	561637	male	C_Se51	dash	563589	male
C710	Front_LH_ParcelRack	561636	female	C_Se51	dash	563590	female
C752_plug	Parcel_Rack	901062	male	C_USB	Parcel_Rack	562069	male
C752_socket	Parcel_Rack	901283	female	C_USB	Parcel_Rack	562070	female
C753_plug	Parcel_Rack	901062	male	CCAN1	FJB	562650	male
C753_socket	Parcel_Rack	901283	female	CCAN1	FJB	562649	female
C766	Parcelrack	561662	male	CCAN2	FJB	562650	male
C766	Parcelrack	561661	female	CCAN2	FJB	562649	female
C768	Parcel_Rack	901062	male	CCAN3	FJB	562650	male
C768	Parcel_Rack	901283	female	CCAN3	FJB	562649	female
C769	Parcel_Rack	901062	male	CCAN4	FJB	562650	male
C769	Parcel_Rack	901283	female	CCAN4	FJB	562649	female
C777	Dash	562477	male	CCust	RJB	562477	male
C777	Dash	562479	female	CCust	RJB	562479	female
C_A60DB	Parcel_Rack	563071	male	CCust.	RJB	562477	male
C_A60DB	Parcel_Rack	563040	female	CCust.	RJB	562479	female
C_A69R	Parcel_Rack	563025	male	CFHPR1	Parcelrack	564560	male
C_A97	Dash	563226	male	CIND-1.A	Parcelrack	560908	female
C_A97	Dash	563613	female	CIND-1.B	Parcelrack	560908	female
C_ALT	Engincmpt.	562581	male	CIND-2.A	Parcelrack	560908	female
C_ALT	Engincmpt.	562583	female	CIND-2.B	Parcelrack	560908	female
C_ALT3	Engincmpt.	562477	male	CIND-11.A	Parcelrack	560908	female
C_ALT3	Engincmpt.	562479	female	CIND-11.B	Parcelrack	560908	female
C_AUDIO_AUX	Parcel_Rack	562557	male	CINDWC-1.A	Parcelrack	560908	female
C_AUDIO_AUX	Parcel_Rack	562558	female	CINDWC-1.B	Parcelrack	560908	female
C_Audio_HDMI_L	Parcel_Rack	901062	male	CL1	FJB	562485	male
C_Audio_HDMI_L	Parcel_Rack	901283	female	CL1	FJB	562486	female
C_Audio_HDMI_R	Parcel_Rack	901062	male	CL58A	Aisle_Section	560898	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
CL58A	Aisle_Section	560900	female	L29	Parcelrack	560898	male
CP1	Passenger_Area	561782	male	L30	Parcelrack	560898	male
CP1	Passenger_Area	561781	female	L30A.A	Parcelrack	560898	male
CP2	Passenger_Area	561782	male	L30B.A	Parcelrack	560898	male
CP2	Passenger_Area	561781	female	L31	Parcelrack	560898	male
CP3	Passengersarea	561782	male	L32	Parcelrack	560898	male
CP3	Passengersarea	561781	female	L33	Parcelrack	560898	male
CP4	Passenger_Area	561782	male	L34	Parcelrack	560898	male
CP4	Passenger_Area	561781	female	L35	Parcelrack	560898	male
CP5	Passenger_Area	561782	male	L36	Parcelrack	560898	male
CP5	Passenger_Area	561781	female	L37	Parcelrack	560898	male
CPA17B	RJB	562337	male	L38	Parcelrack	560898	male
CPA17B	RJB	562338	female	L39	Parcelrack	560898	male
CSO53	Rear_axle_cmpt.	561690	male	L40	Parcelrack	560898	male
CSO53	Rear_axle_cmpt.	561566	female	L41	Parcelrack	560898	male
CSW102	Rear_vehicule	562549	male	L42	Parcelrack	560898	male
CSW102	Rear_vehicule	562550	female	L43	Parcelrack	560898	male
CSX1	Engine_Cmpt	563135	male	L44	Parcelrack	560898	male
CSX1	Engine_Cmpt	563134	female	L45	Parcelrack	560898	male
CSX3	Engine_Cmpt	563135	male	L46	Parcelrack	560898	male
CSX3	Engine_Cmpt	563134	female	L47	Parcelrack	560898	male
CT_IN	Rear_Vehicle	560167	male	L48	Parcelrack	560898	male
CT_IN	Rear_Vehicle	560159	female	L49	Parcelrack	560898	male
CT_IN2	Engine_Cmpt	560167	male	L50	Parcelrack	560898	male
CT_IN2	Engine_Cmpt	560159	female	L51	Parcelrack	560898	male
CT_Out	Rear_Vehicle	560233	female	L52	Parcelrack	560898	male
EI	Enginectmpt.	563739	male	L52	Parcelrack	560900	female
L1A	Engine_Cmpt	560774	male	L52A	Parcelrack	560898	male
L16.A	Frontroof	562615	female	L53	Parcelrack	560898	male
L16.B	Frontroof	562615	female	L53	Parcelrack	560900	female
L17.A	Frontroof	562615	female	L53A	Parcelrack	560898	male
L17.B	Frontroof	562615	female	L54	Parcelrack	560898	male
L18	Entrance_Door	562549	male	L54	Parcelrack	560900	female
L19	Entracedoor	562486	female	L54A	Parcelrack	560898	male
L20	Entracedoorstep	562486	female	L55	Parcelrack	560898	male
L21	Upper_front	562486	female	L55	Parcelrack	560900	female
L22	Upper_front	562486	female	L55A	Parcelrack	560898	male
L23	Upper_front	562486	female	L56	Parcelrack	560898	male
L24	Upper_front	562486	female	L56	Parcelrack	560900	female
L25	Upper_front	562486	female	L56A	Parcelrack	560898	male
L26	Upper_front	562486	female	L57	Parcelrack	560898	male
L27	Upper_front	562486	female	L57	Parcelrack	560900	female
L28	Parcelrack	560898	male	L57A	Parcelrack	560898	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
L58	Parcelrack	560898	male	L144	Parcelrack	561186	male
L58	Parcelrack	560900	female	L145	Parcelrack	561186	male
L58A	Parcelrack	560898	male	L146	Parcelrack	561186	male
L63	Front_Side_LH	562155	male	L147	Parcelrack	561186	male
L64	Outside_Front_RH	562155	male	L148	Parcelrack	561186	male
L64X	Aisle_Section	560898	male	L149	Parcelrack	561186	male
L65	Outside_Front_LH	562155	male	L150	Parcelrack	561186	male
L66	Out_Side_Front_LH	562155	male	L151	Parcelrack	561186	male
L67	4th_Lugg_Cmpt	562155	male	L152	Parcelrack	561186	male
L68	4th_Lugg_Cmpt	562155	male	L153	Parcelrack	561186	male
L69	4th_Lugg_Cmpt	562155	male	L154	Parcelrack	561186	male
L70	4th_Lugg_Cmpt	562155	male	L155	Parcelrack	561186	male
L72	Rear_Vehicle	562155	male	L156	Parcelrack	561186	male
L74	Rear_Vehicle	562155	male	L157	Parcelrack	561186	male
L75	Rearenginedoor	562155	male	L158	Parcelrack	561186	male
L76	Rear_engine_door	562155	male	L173	Parcelrack	563590	female
L81.A	Rear_Vehicle	562835	female	L174A	Parcelrack	563590	female
L81.B	Rear_Vehicle	562834	male	L175	Engine_Cmpt.	563590	female
L82A	Rearvehicule	562348	female	L176	5th_Lugg_Cmpt	561247	male
L83A	Rearvehicule	562348	female	L177	5th_Lugg_Cmpt	561247	male
L84	Rear_roof	562486	female	L178	3rd_Lugg_Cmpt	561247	male
L85	Rear_roof	562486	female	L179	3rd_Lugg_Cmpt	561247	male
L86	Rear_roof	562486	female	L180	2nd_Lugg_Cmpt	561247	male
L87	Rear_roof	562486	female	L181	2nd_Lugg_Cmpt	561247	male
L88	Rear_roof	562486	female	L182	1st_Lugg_Cmpt	561247	male
L89	Rear_roof	562486	female	L183	1st_Lugg_Cmpt	561247	male
L90	Rear_roof	562486	female	L184	Servicecmpt.	561247	male
L93.A	Engine_Cmpt.	563069	female	L185.A	Servicecmpt.	561539	male
L93.B	Engine_Cmpt.	563069	female	L185.B	Servicecmpt.	561539	male
L94.A	Engine_Cmpt.	563069	female	L186.A	Dash	561539	male
L94.B	Engine_Cmpt.	563069	female	L186.B	Dash	561539	male
L95	Outside_Front_LH	562485	male	L187	Engine_Cmpt	561690	male
L95A	Outside_Front_LH	562485	male	L188	Service_Cmpt	562486	female
L96	Outside_Front_RH	562485	male	L193.A	Dash	560488	female
L96A	Outside_Front_RH	562485	male	L193.B	Dash	560488	female
L97.A	Outside_Front_LH	563069	female	L194.A	Dash	562019	female
L97.B	Outside_Front_LH	563069	female	L194.B	Dash	560488	female
L98.A	Entrance_Door	563069	female	L195.A	Dash	560488	female
L98.B	Outside_Front_RH	563069	female	L195.B	Dash	560488	female
L140	Lavatory	561247	male	L199	Enginecmpt.	562848	male
L141	Upper_front	561247	male	L201	Upper_front	561247	male
L142	Lavatory	562006	male	L202	Upper_front	561247	male
L143	Parcel_rack	561186	male	L203	RH_Console	561690	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
L204	Parcel_Rack_RH	562803	male	L604	Luggage_Cmpt	562155	male
L205	Enginect.	562485	male	L605	Luggage_Cmpt	562155	male
L206	Parcel_Rack_RH	562803	male	L606	Luggage_Cmpt	562155	male
L211	Entrance_Door_step	562486	female	L607	Luggage_Cmpt	562155	male
L243	Parcelrack	561186	male	L634	Aisle_Section	560898	male
L244	Parcelrack	561186	male	L635	Aisle_Section	560898	male
L245	Parcelrack	561186	male	L650.A	Aisle_Section	560898	male
L246	Parcelrack	561186	male	L660_1	Rear_Galley	560898	male
L247	Parcel_rack	561186	male	L660_2.A	Rear_Galley	560898	male
L248	Parcelrack	561186	male	L660_3.A	Rear_Galley	560898	male
L249	Parcelrack	561186	male	L661.A	Rear_Galley	560081	female
L250	Parcel_rack	561186	male	L661.B	Rear_Galley	560081	female
L251	Parcel_rack	561186	male	Mic_Driver_1.A	Parcel_rack	560999	male
L252	Parcelrack	561186	male	Mic_Driver_2.A	Parcel_rack	560999	male
L253	Parcel_rack	561186	male	Mic_Driver_3.A	Parcel_rack	560999	male
L254	Parcelrack	561186	male	Mic_Guide_1.A	Parcel_rack	560999	male
L255	Parcel_rack	561186	male	Mic_Guide_2.A	Parcel_rack	560999	male
L256	Parcelrack	561186	male	Mic_Guide_3.A	Parcel_rack	560999	male
L257	Parcelrack	561186	male	Mo3	Dash	561667	female
L258	Parcel_rack	561186	male	Mo4	Dash	562076	male
L282	Engine_Cmpt	561690	male	Mo5	Upper_front	561550	male
L285.A	Rear_Vehicle	562835	female	Mo6	Front_vehicle	561690	male
L285.B	Rear_Vehicle	562834	male	Mo7	Cond_Cmpt	563691	male
L286.A	Rear_Vehicle	562835	female	Mo8	Cond_Cmpt	563691	male
L286.B	Rear_Vehicle	562834	male	Mo10	Parcel_rack	561515	male
L290	Engine_door	562565	female	Mo11	Parcel_rack	561515	male
L291	Engine_door	562565	female	Mo12	Engine_Cmpt	561690	male
L298A	Enginect.	563590	female	Mo13	Engine_Cmpt	561690	female
L306	RJBcmpt.	561247	male	Mo14	Engine_Cmpt	561566	female
L309.	Rear_LH_Lugg	564576	male	Mo15	Front_Ceiling	560900	female
L309D.	Drivers_Area	564576	male	Mo16	Front_Ceiling	560900	female
L310.	Rear_LH_Lugg	564576	male	Mo17	RH_Console	563626	male
L310D.	Drivers_Area	564576	male	Mo18	Fr_Service_Door	562474	male
L314	Front_vehicle	562789	male	Mo19	Fr_Service_Door	562474	male
L315	Front_vehicle	562789	male	Mo20	Fr_Service_Door	562474	male
L319	Under_WCL_platform	561247	male	Mo21	Upper_front	561186	male
L350A.A	Rearaxlecmpt.	564552	male	Mo22	RH_Console	561186	male
L350A.B	Rearaxlecmpt.	563340	male	Mo24	RH_Console	562348	female
L350A.C	Rearaxlecmpt.	562251	male	Mo25	RH_Console	562348	female
L600	Luggage_Cmpt	562155	male	Mo27	Cond_Cmpt	563691	male
L601	Luggage_Cmpt	562155	male	Mo28	Cond_Cmpt	563691	male
L602	Luggage_Cmpt	562155	male	Mo54	Service_Cmpt	562474	male
L603	Luggage_Cmpt	562155	male	Mo61	Parcel_rack	561248	female

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
Mo62	FrontHatch	562486	female	R37	Dash	564496	male
Mo63	RearHatch	562486	female	R38	FJB	564496	male
Mo65	Enginecmpt.	568089	male	R40	RJB	564496	male
Mo67	Enginecmpt.	568089	male	R47	Parcelrack	564496	male
Mo68	Enginecmpt.	568089	male	R72	5th_Bay	563409	male
Mo69	Enginecmpt.	568089	male	R73	5th_Bay	563409	male
Mo70	Enginecmpt.	568089	male	R_12VISS	Parcel_rack	564496	male
Mo71	Enginecmpt.	568089	male	RadioVolvo1_933.A	Parcel_rack	563960	male
Mo72	Enginecmpt.	568089	male	RadioVolvo1_933.B	Parcel_rack	563962	male
Mo73	Enginecmpt.	568089	male	RadioVolvo1_933.C1	Parcel_rack	563956	male
PC1	FJB	562650	male	RadioVolvo1_933.C2	Parcel_rack	563957	male
PC1	FJB	562649	female	RadioVolvo1_933.C3	Parcel_rack	563958	male
PF	FJB	561782	male	RadioVolvo2_933.A	Parcel_rack	563960	male
PF	FJB	561781	female	RadioVolvo2_933.B	Parcel_rack	563962	male
PF1	Passenger_Area	561782	male	RadioVolvo2_933.C1	Parcel_rack	563956	male
PF1	Passenger_Area	561781	female	RadioVolvo2_933.C2	Parcel_rack	563957	male
PF1A	Passenger_Area	561782	male	RadioVolvo2_933.C3	Parcel_rack	563958	male
PF1A	Passenger_Area	561781	female	RadioVolvo3_933.A	Parcel_rack	563960	male
Pot1.A	Dash	560488	female	RadioVolvo3_933.B	Parcel_rack	563962	male
Pot1.B	Dash	560488	female	RadioVolvo3_933.C1	Parcel_rack	563956	male
Pot1.C	Dash	560488	female	RadioVolvo3_933.C2	Parcel_rack	563957	male
Pot2	Dash	561550	male	RadioVolvo3_933.C3	Parcel_rack	563958	male
PR	Parcelrack	561782	male	Res3.A	ParcelRack	563590	female
PR	Parcelrack	561781	female	Res4	RH_Console	563590	female
PR1	Passenger_Area	561782	male	Res6	FJB	563590	female
PR1	Passenger_Area	561781	female	Res6A	FJB	563589	male
PR1A	Passenger_Area	561782	male	Res6A	FJB	563590	female
PR1A	Passenger_Area	561781	female	Res6B	FJB	563589	male
R3	RJB	563409	male	Res6B	FJB	563590	female
R4	FJB	564496	male	Res7	dash	563590	female
R5	RJB	564496	male	Res15	Engine_Cmpt	561782	male
R12	Evap_Cmpt	563409	male	Res31	Ureacmpt.	562350	male
R20	RJB	564496	male	Res32	Ureacmpt.	563764	female
R21	FJB	560525	male	Res46	FJB	563590	female
R23A	FJB	564496	male	Res47	FJB	563590	female
R26	Evap_Cmpt	564496	male	Res53	dash	563590	female
R27	Dash	564496	male	Res99	dash	563590	female
R28	FJB	564496	male	Se2	Service_Cmpt	561566	female
R29	RJB	563409	male	Se4	Window_RH	561477	female
R30	FJB	564496	male	Se5	Window_RH	561477	female
R31	FJB	564496	male	Se6	Window_RH	561477	female
R34	RJB	564210	male	Se7	Window_LH	561477	female
R36	Dash	564496	male	Se8	Window_LH	561477	female

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
Se9	Window_LH	561477	female	Se65	Dash	564042	female
Se10	FJB	561477	female	Se66	FJB	564039	female
Se11.A	Cond_Cmpt	560082	female	Se67	Frontaxlecmpt.	563159	female
Se11.B	Cond_Cmpt	560082	female	Se69	Frontaxlecmpt.	563159	female
Se11.C	Cond_Cmpt	560082	female	Se74	Rear_Axle_Cmpt	563340	male
Se13	Engine_Cmpt	562350	male	Se79	Front_Axle	563340	male
Se14.A	Driver_Area	561782	male	Se89	EngineCmpt	562350	male
Se14.B	Driver_Area	561781	female	Se94	WCLdoor	562877	female
Se15	RH_Console	560898	male	Se100	WCLdoor	562479	female
Se17	Entrance_Door	560081	female	shell1_1618	Driver_Area	562471	male
Se18	Servicecmpt.	561566	female	So3	RH_Console	641385	male
Se19_P	Service_Cmpt	563677	male	So4	RH_Console	641385	male
Se19_S	Service_Cmpt	563677	male	So5	RH_Console	641385	male
Se20	Evap_Cmpt	562426	male	So6	RH_Console	641385	male
Se21	Dash	561248	female	So7	Service_Cmpt	561566	female
Se23	Engine_Cmpt	563159	male	So8	Servicecmpt.	641385	male
Se24	Evap_Cmpt	563758	female	So9	Enginecmpt.	560016	female
Se25	Passenger_Area	561248	female	So10	Cond_Cmpt	562485	male
Se28	Pneumatic_plate	561690	male	So11	Cond_Cmpt	561566	female
Se29	Engine_Cmpt	561566	female	So13	Evap_Cmpt	563204	female
Se30	Enginedoor	562877	female	So14	Servicecmpt.	641385	male
Se31	Enginedoor	562877	female	So15	Servicecmpt.	641385	male
Se32	Rear_Axle_Cmpt	562426	male	So16	Servicecmpt.	641385	male
Se33	Rear_Axle_Cmpt	562856	male	So17	Servicecmpt.	562848	male
Se34	Rear_Axle_Cmpt	562426	male	So18	Pneumatic_plate	641385	male
Se35	Rear_Axle_Cmpt	562426	male	So19	Pneumatic_plate	641385	male
Se36	Rear_Axle_Cmpt	562427	male	So20	Servicecmpt.	641385	male
Se37	Front_Axle_LH	641132	female	So21	Front_Axle_Cmpt	564046	female
Se38	Front_Axle_RH	641132	female	So22	Front_Axle_Cmpt	564046	female
Se39	Rear_Axle_LH	641132	female	So23	Rear_Axle_Cmpt	564046	female
Se40	Rear_Axle_LH	641132	female	So24	Rear_Axle_Cmpt	564046	female
Se41	Condensor_cmpt.	562877	female	So27	Rearaxlecmpt.	564045	female
Se45	Servicecmpt.	563409	male	So50	Rearaxlecmpt.	564046	female
Se46	Rearaxlecmpt.	562348	female	So52	Rearaxlecmpt.	564045	female
Se49	Engine_Cmpt	561690	male	So54	Enginecmpt.	564045	female
Se51	Driverseat	563589	male	spBar4	Enginecmpt.	564135	male
Se53	Service_Cmpt	563159	female	spBar5	Enginecmpt.	564135	male
Se54	Service_Cmpt	563159	female	spBar6	Enginecmpt.	564135	male
Se55	Service_Cmpt	563159	female	spBar7	Enginecmpt.	564135	male
Se56	WCLdoor	562479	female	spBar11	Engine_Cmpt.	564135	male
Se60	Service_Cmpt	563409	male	spBar12	Engine_Cmpt.	564135	male
Se63	Rearaxlecmpt.	641132	female	spBar13	Enginecmpt.	564135	male
Se64	Rearaxlecmpt.	641132	female	spBar14	Enginecmpt.	564135	male

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
spBar15	Enginectpt.	564135	male	Sub2.A	Passenger_Area	564004	female
spBar16	Enginectpt.	564135	male	Sw1.C258	Driver_Area	561188	female
spBar19	Condensorcmt.	564135	male	Sw1.C259	Driver_Area	561186	male
spBar20	Condensorcmt.	564135	male	Sw2	Dash	562763	male
spBar21	Condensorcmt.	564135	male	Sw3	Dash	562763	male
spBar22	Enginectpt.	564135	male	Sw4	Dash	562763	male
spBar23	Enginectpt.	564135	male	Sw5	Dash	562763	male
spBar24	Enginectpt.	564135	male	Sw6	Dash	562763	male
Spk1_L	Parcel_Rack_LH	563994	male	Sw10A	LH_Console	562763	male
Spk1_R	Parcel_Rack_RH	563994	male	Sw12	Dash	562763	male
Spk2_L	Parcel_Rack_LH	563994	male	Sw14	Dash	562763	male
Spk2_R	Parcel_Rack_RH	563994	male	Sw16	Dash	562763	male
Spk3_L	Parcel_Rack_LH	563994	male	Sw17	Dash	562763	male
Spk3_R	Parcel_Rack_RH	563994	male	Sw18A	LH_Console	562763	male
Spk4_L	Parcel_Rack_LH	563994	male	Sw20	Dash	562763	male
Spk4_R	Parcel_Rack_RH	563994	male	Sw21	Dash	562763	male
Spk5_L	Parcel_Rack_LH	563994	male	Sw24	Dash	562763	male
Spk5_R	Parcel_Rack_RH	563994	male	Sw25	Dash	562763	male
Spk6_L	Parcel_Rack_LH	563994	male	Sw26	Dash	562763	male
Spk6_R	Parcel_Rack_RH	563994	male	Sw27	Dash	562763	male
Spk7_L	Parcel_Rack_LH	563994	male	Sw29	Dash	562763	male
Spk7_R	Parcel_Rack_RH	563994	male	Sw30	RJB	563135	male
Spk8_L	Parcel_Rack_LH	563994	male	Sw32	Dash	561477	female
Spk8_R	Parcel_Rack_RH	563994	male	Sw33	Dash	561476	male
Spk9_L	Parcel_Rack_LH	563994	male	Sw34	Outside_Front_RH	562477	male
Spk9_R	Parcel_Rack_RH	563994	male	Sw35	Console	562763	male
Spk10_L	Parcel_Rack_LH	563994	male	Sw38	LH_Console	562763	male
Spk10_R	Parcel_Rack_RH	563994	male	Sw39.A	RJB	562403	female
Spk11_L	Parcel_Rack_LH	563994	male	Sw39.B	RJB	562403	female
Spk11_R	Parcel_Rack_RH	563994	male	Sw40	LH_Console	561690	male
Spk12_L	Parcel_Rack_LH	563994	male	Sw41	LH_Console	562749	male
Spk12_R	Parcel_Rack_RH	563994	male	Sw42	Lugg_Cmpt	561636	female
Spk13_L	Parcel_Rack_LH	563994	male	Sw43	LH_Console	561690	male
Spk13_R	Parcel_Rack_RH	563994	male	Sw44.A	FJB	562403	female
Spk14_L	Parcel_Rack_LH	563994	male	Sw44.B	FJB	562403	female
Spk14_R	Parcel_Rack_RH	563994	male	Sw45.A	5th_Lugg_Cmpt	562485	male
Spk15_L	Parcel_Rack_LH	563994	male	Sw45.B	5th_Lugg_Cmpt	562486	female
Spk15_R	Parcel_Rack_RH	563994	male	Sw46.A	5th_Lugg_Cmpt	562485	male
Spk16_L	Parcel_Rack_LH	563994	male	Sw46.B	5th_Lugg_Cmpt	562486	female
Spk16_R	Parcel_Rack_RH	563994	male	Sw47.A	3rd_Lugg_Cmpt	562485	male
SpkDr_L	Parcel_Rack_LH	563994	male	Sw47.B	3rd_Lugg_Cmpt	562486	female
SpkDr_R	Parcel_Rack_RH	563994	male	Sw48.A	3rd_Lugg_Cmpt	562485	male
Sub1.A	Passenger_Area	564004	female	Sw48.B	3rd_Lugg_Cmpt	562486	female

# CONNECTORS LIST

No	Location	Part #	Gender	No	Location	Part #	Gender
Sw49.A	2nd_Lugg_Cmpt	562485	male	Sw156	LH_Console	562763	male
Sw49.B	2nd_Lugg_Cmpt	562486	female	Sw157	Dash	562763	male
Sw50.A	2nd_Lugg_Cmpt	562485	male	Sw158	Dash	562763	male
Sw50.B	2nd_Lugg_Cmpt	562486	female	Sw629	Dash	562763	male
Sw51.A	1st_Lugg_Cmpt	562485	male	Sw660	Rear_Galley	562763	male
Sw51.B	1st_Lugg_Cmpt	562486	female	Sw661	Rear_Galley	562763	male
Sw52.A	1st_Lugg_Cmpt	562485	male	Sw662	Dash	562763	male
Sw52.B	1st_Lugg_Cmpt	562486	female	Sw663	Rear_Galley	562763	male
Sw55.A	Lavatory	560488	female	Sw670	dash	562763	male
Sw55.B	Lavatory	560488	female	sym698_166.A	Parcel_rack	564489	female
Sw56.A	Lavatory	560488	female	sym698_166.B	Parcel_rack	562706	female
Sw56.B	Lavatory	560488	female	sym698_166.C	Parcel_rack	562706	female
Sw58	Engine_Cmpt.	563135	male	sym699_166.A	Parcel_rack	564489	female
Sw59	Enginectmpt.	563135	male	sym699_166.B	Parcel_rack	562706	female
Sw63A	LHConsole	562763	male	sym699_166.C	Parcel_rack	562706	female
Sw64.A	Service_Cmpt	560815	female	sym700_166.A	Parcel_rack	564489	female
Sw64.B	Service_Cmpt	560815	female	sym700_166.B	Parcel_rack	562706	female
Sw82	RJB	563135	male	sym700_166.C	Parcel_rack	562706	female
Sw83.A	Dash	560082	female	sym812_291.A	Parcelrack	565180	female
Sw83.B	Dash	560815	female	tab69	Parcelrack	561626	N/A
Sw83.C	Dash	560082	female	Tab70a	Parcelrack	561626	N/A
Sw83.D	Dash	560815	female	Tab70b	Parcelrack	561626	N/A
Sw85	LH_Console	562749	male	tab71a	Parcelrack	561626	N/A
Sw95.A	WCLdoor	562615	female	TermL150	Parcel_rack	562505	N/A
Sw95.B	WCLdoor	562615	female	TermL248	Parcel_rack	562505	N/A
Sw95.C	WCLdoor	562615	female	VECF1	FJB	563186	male
Sw96.A	WCL_Door	562615	female	VECF2	FJB	563183	male
Sw96.B	WCL_Door	562615	female	VECF3	FJB	563185	male
Sw96.C	WCLdoor	562615	female	VECF4	FJB	563182	male
Sw97.A	WCLsystem	562615	female	VECF9	FJB	563448	male
Sw97.B	WCLsystem	562615	female	VECF10	FJB	563181	male
Sw97.C	WCLsystem	562615	female	VECF11	FJB	563184	male
Sw98.A	WCLsystem	562615	female	VECF12	FJB	563187	male
Sw98.B	WCLsystem	562615	female	VECR1	RJB	563186	male
Sw98.C	WCLsystem	562615	female	VECR2	RJB	563183	male
Sw100	dash	562763	male	VECR3	RJB	563185	male
Sw107	dash	562763	male	VECR4	RJB	563182	male
Sw108	dash	562763	male	VECR4.	RJB	563182	male
Sw124	DashBoard	562763	male	VECR9	RJB	563448	male
Sw125.A	Service_Cmpt	561457	female	VECR10	RJB	563181	male
Sw125.B	Service_Cmpt	561457	female	VECR11	RJB	563184	male
Sw137	Dash	562763	male	VECR12	RJB	563187	male
Sw149	Dash	562763	male	VECT3	Rear_vehicule	563718	male

