



PREVOST

ENREGISTRÉ - REGISTERED
ISO 9001 & ISO 14001

MAINTENANCE INFORMATION Mi99-42



| | |
|---|---------------------|
| DATE : December 1999 | SECTION : 22 |
| SUBJECT : IMPROVED HOSES FOR AIR CONDITIONING SYSTEM | |

Important Notice: This modification is recommended by Prévost Car to increase your vehicle's performance. Note that no reimbursement will be awarded for carrying out this modification.

APPLICATION

| Modèle | VIN |
|---|---|
| Coaches H3-41 & H3-45 Model Year : 1994 - 2000 | From 2P9H33495R100 <u>1012</u> up to 2PCH3349XY101 <u>3620</u> incl. |
| Bus Shells VIP Model Year : 1994 - 2000 | From 2P9V3340XR100 <u>1382</u> up to 2PCV33498Y101 <u>3618</u> incl. |
| Coaches XL-40 & XL-45 Model Year : 1994 - 2000 | From 2P9L33402R100 <u>1934</u> up to 2PCL33493Y102 <u>7045</u> incl. |
| Bus Shells XL-40, XL-45 & XL-45 Entertainer Model Year : 1994 - 2000 | From 2P9E33495R100 <u>1935</u> up to 2PCE33492Y102 <u>7028</u> incl. |
| Coaches XLII Model Year : 2000 | From 2PCX33495Y102 <u>6951</u> up to 2PCX33490Y102 <u>7117</u> incl. |
| Bus Shells XLII Model Year : 2000 | From 2PCW33496Y102 <u>6856</u> up to PCW33402Y102 <u>7133</u> incl. |

DESCRIPTION

New, longer lasting A/C hoses are available for purchase. These new hoses replace the old ones without any modifications.

Note : The new hoses are completely interchangeable with the older one. Refer to your "Parts Manual" to identify the hoses.

MATERIAL

| Old hoses | New hoses |
|-----------|-----------|
| 373269 | 453573 |
| 373270 | 453574 |
| 373271 | 453575 |
| 373372 | 453567 |
| 452387 | 453568 |
| 452526 | 453576 |
| 452527 | 453577 |
| 452528 | 453578 |
| 452529 | 453569 |
| 452554 | 453570 |
| 452555 | 453579 |
| 452556 | 453580 |
| 452625 | 453571 |
| 452725 | 453572 |
| 452927 | 453581 |
| 453347 | 453582 |
| 453353 | 453583 |

Note : *Material can be obtained through regular channels.*

Waste disposal :

Discard according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)