No	Location	Part #	Gender	No	Location	Part #	Gender
C71	FJB	561646	male	A45.J1	FJB	563133	male
C71	FJB	561645	female	L94.A	EngineCmpt.	563069	female
C397	RJB	562285	male	L94.B	EngineCmpt.	563069	female
C397	RJB	562282	female	A46.J2	FJB	563132	male
A36.JC	FJB	562957	male	A46.J3	FJB	562957	male
A36.JA	FJB	562767	male	A46.J1	FJB	563133	male
Sw59	EngineCmpt.	562485	male	C72	ServiceCmpt.	561646	male
C152	CondensorCmpt.	561611	male	C72	ServiceCmpt.	561645	female
C152	CondensorCmpt.	561610	female	Sw5	Dash	562763	male
A54.J2	Evap.Cmpt.	563132	male	Mo21	FrontRoof	561186	male
A54.J3	Evap.Cmpt.	562957	male	Mo22	RightHandConsole	561186	male
A54.J1	Evap.Cmpt.	563133	male	A47.J2	RightHandConsole	563132	male
C171	FJB	561646	male	A47.J3	RightHandConsole	562957	male
C171	FJB	561645	female	A47.J1	RightHandConsole	563133	male
A43.J1	FJB	562767	male	Mo3	Dash	561667	female
A44.J2	FJB	563132	male	C2	ServiceCmpt.	563580	male
A44.J3	FJB	562957	male	C2	ServiceCmpt.	563581	female
A44.J1	FJB	563133	male	C100	5thLuggCmpt.	563589	male
C45	FJB	561643	male	C100	5thLuggCmpt.	563590	female
C45	FJB	561642	female	C101	ServiceCmpt.	561690	male
C4	ServiceCmpt.	563580	male	C101	ServiceCmpt.	561566	female
C4	ServiceCmpt.	563581	female	C581	UnderdashBoard	562777	male
A41.J1	FJB	562767	male	Sw81.A	Dash	562905	male
C91	RJB	562285	male	Sw81.B	Dash	562905	male
C91	RJB	562282	female	Sw24	Dash	562763	male
Se2	EngineCmpt.	562486	female	Pot1.A	Dash	560488	female
Se1	EngineCmpt.	562486	female	Pot1.B	Dash	560488	female
Se3	RJB	562486	female	Pot1.C	Dash	560488	female
A52.J2	RJB	563132	male	Sw15	Dash	562763	male
A52.J3	RJB	562957	male	Mo2	EngineCmpt.	561782	male
A52.J1	RJB	563133	male	L65	Outside_Front_LH	562155	male
A42.J1	FJB	562767	male	L66	Outside_Front_LH	562155	male
Sw22	Dash	562763	male	L64	Outside_Front_RH	562155	male
Sw2	Dash	562763	male	L63	Outside_Front_RH	562155	male
A51.J2	RJB	563132	male	Sw3	Dash	562763	male
A51.J3	RJB	562957	male	Mo4	Dash	562076	male
A51.J1	RJB	563133	male	Sw18	Dash	562763	male
C119	EngineDoor	561607	male	C21A	RJB	561646	male
C119	EngineDoor	561606	female	C21A	RJB	561645	female
C120	EngineDoor	561607	male	A5	ServiceCmpt.	562428	female
C120	EngineDoor	561606	female	C463	EngineCmpt.	562570	female
A45.J2	FJB	563132	male	C463	EngineCmpt.	562571	male
A45.J3	FJB	562957	male	Se32	EngineCmpt.	563057	male

PREVOST	WIRING DIAGRAM	No:	D061040 Page G.1	REMSION 06

No	Location	Part #	Gender	No	Location	Part #	Gender
Se33	EngineCmpt.	562856	male	C1	FJB	563590	female
Se34	EngineCmpt.	563057	male	C3	RJB	563589	male
Se35	EngineCmpt.	563057	male	C3	RJB	563590	female
L175	RJB	561247	male	C87	RearRoof	561637	male
Se30	EngineCmpt.	561690	female	C87	RearRoof	561636	female
Se31	EngineCmpt.	561690	female	C426	EngineCmpt	561782	male
L176	5thLuggCmpt.	561247	male	C426	EngineCmpt	561781	female
L177	5thLuggCmpt.	561247	male	C12_plug	RJB	562485	male
L178	3rdLuggCmpt.	561247	male	C12_socket	RJB	562486	female
L179	3rdLuggCmpt.	561247	male	C96	FrAxleAccessories	561583	male
L180	2ndLuggCmpt.	561247	male	C96	FrAxleAccessories	561585	female
L181	2ndLuggCmpt.	561247	male	C97	RrAxleAccInsidePVC	561607	male
L182	1stLuggCmpt.	561247	male	C97	RrAxleAccInsidePVC	561606	female
L183	1stLuggCmpt.	561247	male	C69	RrAxleInsidePVC	561607	male
L184	ServiceCmpt.	561247	male	C69	RrAxleInsidePVC	561606	female
C74	ServiceCmpt.	561645	female	C15	5thLuggCmpt.	561646	male
C74	ServiceCmpt.	561646	male	C15	5thLuggCmpt.	561645	female
C230	EngineCmpt.	562485	male	C17	RJB	561986	male
C230	EngineCmpt.	562486	female	C17	RJB	561987	female
Sw60	EngineCmpt.	561566	female	C18	FJB	561986	male
Se12	EngineCmpt.	561690	female	C18	FJB	561987	female
So1	EngineCmpt.	561566	female	C19	RJB	561986	male
Mo16	FrontRoof	560900	female	C19	RJB	561987	female
Mo15	FrontRoof	560900	female	Se23	EngineCmpt.	563159	male
Sw8	Dash	562763	male	Se24	EngineCmpt.	563159	male
Sw9	Dash	562763	male	A36.JB	FJB	562765	male
Sw38	LeftHandConsole	562763	male	Se21	Dash	561248	female
Sw41	LeftHandConsole	562749	male	A50.J2	RJB	563132	male
Sw4	Dash	562763	male	A50.J3	RJB	562957	male
C6	ServiceCmpt.	563582	male	A50.J1	RJB	563133	male
C6	ServiceCmpt.	563583	female	L76	Rear_Engine_Door	562155	male
A3	Dash	562363	male	L74	Rear_Vehicle	562155	male
Sw23	Dash	562763	male	L75	Rear_Vehicle	562155	male
Sw58	EngineCmpt.	562581	male	L72	Rear_Vehicle	562155	male
L193.B	Dash	560488	female	L71	Rear_Engine_Door	562601	male
L194.A	Dash	562019	female	L77	Rear_Engine_Door	562601	male
L194.B	Dash	560488	female	L78	Rear_Engine_Door	562601	male
L195.B	Dash	560488	female	L79	Rear_Engine_Door	562601	male
Sw16	Dash	562763	male	L80	Rear_Engine_Door	562601	male
So7	ServiceCmpt.	561566	male	L82	Rear_Engine_Door	562348	female
L187	EngineCmpt.	561690	male	C22	RJB	561847	male
Mo1	EngineCmpt.	561690	female	C22	RJB	561862	female
C1	FJB	563589	male	C48	ServiceCmpt.	561690	male

PREVOST	WIRING DIAGRAM	No.	L		REMSION
FRE VUS 1	WIKING DIAGRAW	No:	D061040	Page G.2	06

No	Location	Part #	Gender	No	Location	Part #	Gender
C48	ServiceCmpt.	561566	female	L81.A	Rear_Engine_Door	562835	female
Se18.A	ServiceCmpt.	560815	female	L81.B	Rear_Engine_Door	562834	male
Se18.B	ServiceCmpt.	560815	female	L73	Rear_Vehicle	562601	male
VECF1	FJB	563186	male	C589	ServiceCmpt.	563088	male
VECF2	FJB	563183	male	C589	ServiceCmpt.	563089	female
VECF3	FJB	563185	male	C590	RHConsole	563088	male
VECF4	FJB	563182	male	C590	RHConsole	563089	female
VECF10	FJB	563181	male	R3	RJB	563409	male
VECF11	FJB	563184	male	R12	Evap.Cmpt.	563409	male
VECF12	FJB	563187	male	R9	Evap.Cmpt.	563409	male
VECR1	RJB	563186	male	R10	Evap.Cmpt.	563409	male
VECR2	RJB	563183	male	R24	FJB	561183	male
VECR3	RJB	563185	male	C246	ServiceCmpt.	563090	male
VECR4	RJB	563182	male	C246	ServiceCmpt.	563091	female
VECR10	RJB	563181	male	C269	RHConsole	563090	male
VECR11	RJB	563184	male	C269	RHConsole	563091	female
VECR12	RJB	563187	male	R16	Dash	561183	male
C24	Evap.Cmpt.	561690	male	Sw11	Dash	562763	male
C24	Evap.Cmpt.	561566	female	A15	Dash	562464	male
Sw64.A	ServiceCmpt.	560815	female	Sw13	Dash	562763	male
Sw64.B	ServiceCmpt.	560815	female	A14.LX	Dash	562766	male
C380	Dash	563180	male	A14.CY	Dash	562765	male
C380	Dash	563347	female	A14.LY	Dash	562767	male
C464	RJB	563180	male	A14.RX	Dash	562767	male
C464	RJB	563347	female	A14.CX	Dash	562957	male
C26_plug	RJB	562485	male	Se11.A	Cond.Cmpt.	560082	male
C26_socket	RJB	562486	female	Se11.B	Cond.Cmpt.	560082	male
C11	ServiceCmpt.	563580	male	Se11.C	Cond.Cmpt.	560082	male
C11	ServiceCmpt.	563581	female	L98.A	Entrance_Door	563069	female
Sw85	LeftHandConsole	562749	male	L98.B	Outside_Front_RH	563069	female
A12	Dash	562464	male	L97.A	Outside_Front_LH	563069	female
L208	Outside_Front_LH	563088	male	L97.B	Outside_Front_LH	563069	female
L209	Outside_Front_RH	563088	male	L27.B	FrontRoof	562286	male
L67	3rdLuggCmpt.	562155	male	L27.A	FrontRoof	561608	female
L68	3rdLuggCmpt.	562155	male	L26.B	FrontRoof	562286	male
L69	3rdLuggCmpt.	562155	male	L26.A	FrontRoof	561608	female
L70	3rdLuggCmpt.	562155	male	L25.B	FrontRoof	562286	male
Mo12	Evap.Cmpt.	561690	male	L25.A	FrontRoof	561608	female
So12	Evap.Cmpt.	561566	female	L24.B	FrontRoof	562286	male
So13	Evap.Cmpt.	563204	female	L24.A	FrontRoof	561608	female
C121	EngineDoor	561690	male	L23.B	FrontRoof	562286	male
C121	EngineDoor	561566	female	L23.A	FrontRoof	561608	female
L83	Rear Engine Door	562348		L22.B	FrontRoof	562286	male

No	Location	Part #	Gender	No	Location	Part #	Gender
L22.A	FrontRoof	561608	female	C34	RightHandConsole	561986	male
L21.B	FrontRoof	562286	male	C34	RightHandConsole	561987	female
L21.A	FrontRoof	561608	female	Sw83.D	Dash	560815	female
L88.B	RearRoof	562286	male	Sw83.A	Dash	560082	female
L84.A	RearRoof	561608	female	Sw83.B	Dash	560815	female
L90.A	RearRoof	561608	female	Sw83.C	Dash	560082	female
L86.A	RearRoof	561608	female	C44_plug	FJB	561577	male
L89.A	RearRoof	561608	female	C44_socket	FJB	561605	female
L85.A	RearRoof	561608	female	R18	FJB	562367	male
L88.A	RearRoof	561608	female	R19	FJB	562367	male
L87.A	RearRoof	561608	female	A18.J2	FJB	562650	male
L96	Outside_Front_RH	562902	female	A18	FJB	562794	male
L95	Outside_Front_LH	562902	female	L173	EngineCmpt.	563268	male
C243	ServiceCmpt.	562789	male	L174	EngineCmpt.	563268	male
C243	ServiceCmpt.	565131	female	So8	ServiceCmpt.	563204	female
C242	ServiceCmpt.	562789	male	L205	Evap.Cmpt.	562485	male
C242	ServiceCmpt.	565131	female	Se25	PassengerArea	561248	female
L59.A	Outside_Front_RH	562623	male	L199	EngineCmpt.	562471	male
L59.B	Outside_Front_RH	562623	male	L200	EngineCmpt.	562471	male
L60.A	Outside_Front_LH	562623	male	L193.A	Dash	560488	female
L60.B	Outside_Front_LH	562623	male	L195.A	Dash	560488	female
L92	EngineCmpt.	562755	male	So11	Cond.Cmpt.	561566	female
L91	EngineCmpt.	562755	male	R17	RJB	562367	male
L84.B	RearRoof	562286	male	A13.J2	FJB	562650	male
L85.B	RearRoof	562286	male	A13.J1	FJB	562794	male
L86.B	RearRoof	562286	male	Sw52	1stLuggCmpt.	562403	female
L87.B	RearRoof	562286	male	Sw44.A	FJB	562403	female
L89.B	RearRoof	562286	male	Se20	Evap.Cmpt.	562426	male
L90.B	RearRoof	562286	male	C21B	RJB	561646	male
R23	RightHandConsole	561183	male	C21B	RJB	561645	female
L62	Outside_Front_LH	562601	male	Sw46.A	5thLuggCmpt.	562403	female
L61	Outside_Front_RH	562601	male	Sw46.B	5thLuggCmpt.	562403	female
C40	Dash	562485	male	Sw45.A	5thLuggCmpt.	562403	female
C40	Dash	562486	female	Sw45.B	5thLuggCmpt.	562403	female
R25	RJB	561183	male	Sw44.B	FJB	562403	female
A53.J2	RJB	563132	male	Sw39.A	RJB	562403	female
A53.J3	RJB	562957	male	Sw39.B	RJB	562403	female
A53.J1	RJB	563133	male	Sw47.A	3rdLuggCmpt.	562403	female
Sw82.A	RJB	561457	female	Sw47.B	3rdLuggCmpt.	562403	female
Sw82.B	RJB	561457	female	Sw48.A	3rdLuggCmpt.	562403	female
Sw82.C	RJB	561457	female	Sw48.B	3rdLuggCmpt.	562403	female
Sw82.D	RJB	561457	female	Sw49.A	2ndLuggCmpt.	562403	female
Se29	EngineCmpt.	561566	female	Sw49.B	2ndLuaaCmpt.	562403	female

No	Location	Part #	Gender	No	Location	Part #	Gender
Sw50.A	2ndLuggCmpt.	562403	female	Reg.D	RJB	560085	female
Sw50.B	2ndLuggCmpt.	562403	female	Reg.C	RJB	560085	female
Sw51.A	1stLuggCmpt.	562403	female	Sw102	Dash	562763	male
Sw51.B	1stLuggCmpt.	562403	female	Sw103	Dash	562763	male
Sw7.A	Cond.Cmpt.	562403	female	C75	4thLuggCmpt	561668	male
Sw7.B	Cond.Cmpt.	562403	female	C75	4thLuggCmpt	561551	female
VECR9	RJB	563448	male	Mo39	5thLuggCmpt.	562076	male
C92	FJB	561640	male	C82	1stLuggCmpt.	561668	male
C92	FJB	561639	female	C82	1stLuggCmpt.	561551	female
Sw52.B	1stLuggCmpt.	562403	female	Mo38	5thLuggCmpt.	562076	male
C279	FJB	562477	male	Mo37	4thLuggCmpt	562076	male
C279	FJB	562479	female	Mo36	4thLuggCmpt	562076	male
L17	FrontRoof	562803	male	Mo35	3rdLuggCmpt.	562076	male
L16	FrontRoof	562803	male	C81	1stLuggCmpt.	561668	male
Mo24	RightHandConsole	562348	female	C81	4thLuggCmpt	561551	female
Mo25	RightHandConsole	562348	female	C86	3rdLuggCmpt.	561668	male
R40	FJBVECF	561183	male	C86	3rdLuggCmpt.	561551	female
A27	ServiceCmpt.	562929	male	C85	3rdLuggCmpt.	561668	male
A28	ServiceCmpt.	562928	male	C85	3rdLuggCmpt.	561551	female
L190	Outside_Front_LH	562069	male	C77	4thLuggCmpt	561668	male
L189	Outside_Front_RH	562069	male	C77	4thLuggCmpt	561551	female
Sw84.A	EngineCmpt.	560488	female	C83	2ndLuggCmpt.	561668	male
Sw84.B	EngineCmpt.	560488	female	C83	2ndLuggCmpt.	561551	female
Sw40	LeftHandConsole	561690	male	C84	2ndLuggCmpt.	561668	male
C398	EngineCmpt.	561690	male	C84	2ndLuggCmpt.	561551	female
C398	EngineCmpt.	561566	female	C291	5thLuggCmpt.	561668	male
C266	RightHandConsole	561583	male	C291	5thLuggCmpt.	561551	female
C266	RightHandConsole	561585	female	C290	5thLuggCmpt.	561668	male
A41.J3		562957	male	C290	5thLuggCmpt.	561551	female
A41.J2		563132	male	Mo26	Entrance_Door	562076	male
A42.J3		562957	male	C360	Dash	561247	male
A42.J2		563132	male	C360	Dash	561248	female
A43.J3		562957	male	C89	RearRoof	561581	male
A43.J2		563132	male	C89	RearRoof	561582	female
Sw106	Entrance_Door	561637	male	So34	EngineCmpt.	561690	male
C281	LeftHandConsole	560852	male	C555	1stLuggCmpt.	561476	male
C281	LeftHandConsole	560851	female	C555	1stLuggCmpt.	561477	female
C172	ServiceCmpt.	561637	male	C556	5thLuggCmpt.	561476	male
C172	ServiceCmpt.	561635	female	C556	5thLuggCmpt.	561477	female
Sw108	LeftHandConsole	562763	male	C500	FJB	562069	male
Sw104	Dash	562763	male	C500	FJB	562070	female
Reg.A	RJB	560815	female	C342	EngineCmpt.	562477	male
Rea.B	RJB	560085	female	C342	EnaineCmpt.	562479	female

PREVOST	WIRING DIAGRAM	No:	D061040 Page	G.5	REMSION 06

No	Location	Part #	Gender	No	Location	Part #	Gender
A49.J2	RJB	563132	male	CC1	ServiceCmpt.	563227	male
A49.J3	RJB	562957	male	CC1	ServiceCmpt.	563614	female
A49.J1	RJB	562767	male	CC2	ServiceCmpt.	563226	male
A24.A	RightHandConsole	561890	male	CC2	ServiceCmpt.	563613	female
A24.B	RightHandConsole	561566	female	Se17.A	RightHandConsole	562019	female
A24	RightHandConsole	561889	female	Se17.B	RightHandConsole	562019	female
Sw122	PassengerArea	562763	male	Se16.A	Entrance_Door	562651	female
C264	Entrance_Door	561637	male	Se16.B	Entrance_Door	562651	female
C264	Entrance_Door	561636	female	L285	Dash	561247	male
CT2	EngineCmpt.	563226	male	A31.A	FJB	562676	male
CT2	EngineCmpt.	563613	female	A31.B	FJB	562675	male
C5	FJB	563589	male	L18.B	Entrance_Door	561539	male
C5	FJB	563590	female	L19.A	RightHandConsole	560488	female
Res3	RJB	563590	female	L19.B	RightHandConsole	560488	female
C3S	RJB	563593	male	L211.A	RightHandConsole	560488	female
C3S	RJB	563590	female	L211.B	RightHandConsole	560488	female
C100S	5thLuggCmpt.	563589	male	Sw99	Dash	562763	male
C100S	5thLuggCmpt.	563590	female	Sw116.A	4thLuggCmpt	560079	female
C1S	FJB	563589	male	Sw116.B	4thLuggCmpt	560079	female
C1S	FJB	563590	female	L287	4thLuggCmpt	561247	male
C5S	FJB	563589	male	Sw128.A	4thLuggCmpt	562403	female
C5S	FJB	563590	female	Sw128.B	4thLuggCmpt	562403	female
C13S	RightHandConsole	563593	male	L288	4thLuggCmpt	561247	male
C13S	RightHandConsole	563590	female	C550	5thLuggCmpt.	561476	male
Res4	RightHandConsole	563590	female	C550	5thLuggCmpt.	561477	female
Res6	FJB	563590	female	C551	5thLuggCmpt.	561476	male
Res5	Dash	563590	female	C551	5thLuggCmpt.	561477	female
A58	FJB	562464	male	C552	3rdLuggCmpt.	561476	male
Sw119	Dash	562763	male	C552	3rdLuggCmpt.	561477	female
MONITOR	Dash	561247	male	C553	2ndLuggCmpt.	561476	male
R30	RJB	561183	male	C553	2ndLuggCmpt.	561477	female
R31	RJB	561183	male	C554	1stLuggCmpt.	561476	male
R32	RJB	561183	male	C554	1stLuggCmpt.	561477	female
R33	RJB	561183	male	C557	3rdLuggCmpt.	561476	male
Sw120	DriverArea	562237	female	C557	3rdLuggCmpt.	561477	female
Sw117.A	5thLuggCmpt.	560079	female	C558	4thLuggCmpt	561476	male
Sw117.B	5thLuggCmpt.	560079	female	C558	4thLuggCmpt	561477	female
L93.A	Rear_Vehicle	563069	female	C559	5thLuggCmpt.	561476	male
L93.B	Rear_Vehicle	563069	female	C559	5thLuggCmpt.	561477	female
A48.J2	RightHandConsole	563132	male	C193	RJB	563589	male
A48.J3	RightHandConsole	562957	male	C193	RJB	563590	female
A48.J1	RightHandConsole	563133	male	C194	FJB	563589	male
Sw121	Dash	562763	male	C194	FJB	563590	female

No	Location	Part #	Gender	No	Location	Part #	Gender
Se50	ServiceCmpt.	562426	male	Mo17	LeftHandConsole	563626	male
C200	FJB	561607	male	A30	RightHandConsole	561889	female
C200	FJB	561606	female	A30.A	RightHandConsole	561611	male
Se52.A	RightHandConsole	560488	female	A32.A	1stLuggCmpt.	561611	male
Se52.B	RightHandConsole	560488	female	Se46	AboveRearAxle	562348	female
Mo51	1stLuggCmpt.	561690	male	A32.C	1stLuggCmpt.	561566	female
So26	ServiceCmpt.	641385	male	So38	1stLuggCmpt.	561566	female
So9	EngineCmpt.	561566	female	Mo50	ServiceCmpt.	561782	male
Mo53	RJB	561248	female	C228	EngineCmpt.	563227	male
C400_plug	EngineCmpt.	561782	male	C228	EngineCmpt.	563614	female
C400_socket	EngineCmpt.	561781	female	C78	EngineCmpt.	561690	male
Mo40	1stLuggCmpt.	561477	female	C78	EngineCmpt.	561566	female
Se45	ServiceCmpt.	563409	male	L203	RightHandConsole	561690	male
C1P		563589	male	Sw1.C258	Dash	561188	female
C1P		563590	female	Sw1.C259	Dash	561186	male
C5P		563589	male	Mo7	Cond.Cmpt.	563600	female
C5P		563590	female	Mo8	Cond.Cmpt.	563600	female
A41		562957	male	R21		561183	male
A42		562957	male	So27		641385	male
A43		562957	male	A1Gen4.A		563975	male
A44		562957	male	A7Gen4		563979	male
A45		562957	male	C717		561646	male
A46		562957	male	C717		561645	female
A47		562957	male	A2Gen4		563984	male
A48		562957	male	Alt2.B		560815	female
A49		562957	male	Alt1.B		560815	female
A53		562957	male	Mo18		562474	male
A52		562957	male	Mo19		562474	male
A50		562957	male	Mo20		562474	male
C3P		563589	male	Mo54		562474	male
C3P		563590	female	Se60		563409	male
A4.A	ServiceCmpt.	562428	female	Sw6		562763	male
A4.B	ServiceCmpt.	561188	female	SwSo1.A		561552	female
Alt1.A	EngineCmpt.	560815	female	SESO1		563159	male
Alt1.B		560815	female	SESO2		562479	female
Alt1.C	EngineCmpt.	562862	female	SESO3		562479	female
Alt2.A	EngineCmpt.	560815	female	A56.J2		563132	male
Alt2.B		560815	female	A56.J3		562957	male
Alt2.C	EngineCmpt.	562862	female	A56.J1		563133	male
Alt3.D	EngineCmpt.	560587	female	SoSo5		641385	male
Alt3.A	EngineCmpt.	560815	female	SoSo1		641385	male
Alt3.B	EngineCmpt.	560086	female	SoSo2		641385	male
Alt3.C	EnaineCmpt.	562862	female	SOSO4		641385	male

No Location	Part #	Gender	No Location	Part #	Gender
MoSo1.A	561967 r	male	A73.J1	563681	male
RSo1.A	561626 f	female	A74	563207	male
RSo1.B	561626 f	female	Res7.A	563590	female
RSo2.A	561626 f	female	Sw103	562763	male
RSo2.B	561626 f	female	C13_plug	563589	male
CS02	561643 r	male	C13_socket	563590	female
CS02	561641 f	female	Res12.A	563590	female
SwSo2	561552 f	female	L187.A	561690	male
CS07	561695 r	male	Sw107.A	561457	female
CS07	561694 f	female	Sw107.B	561457	female
SESO5	562479 f	female	Sw107.C	561457	female
SESO6	562479 f	female	Sw107.D	561457	female
A57.J2	563132 r	male	Sw107.E	561457	female
A57.J3	562957 r	male	Sw107.F	561457	female
A57.J1	563133 r	male	Sw107.G	561457	female
MOSO2.A	561967 r	male	Sw107.H	561457	female
RSo3.A	561626 f	female	Sw107.J	561457	female
RSo3.B	561626 f	female	Sw107.K	561457	female
RSo4.A	561626 f	female	CS01	562581	male
RSo4.B	561626 f	female	CS01	562583	female
CS05	561847 r	male	CS01S	562581	male
CS05	561862 f	female	CS01S	562583	female
A6	563629 f	female	SoSo6	641385	male
Se36	563628 f	female	SoSo3	641385	male
C8	562884 f	female	Mo44	561477	female
C8	562877 f	female	C10	562477	male
C7	562884 f	female	C10	562479	female
C7	562877 f	female	VECF9	563448	male
A72.J2	563678 r	male	Se19.A	563677	male
A72.J3	563679 r	male	Se49.A	563677	male
A72.J4	563680 r	male	C168	561890	male
A72.J1	563675 r	male	C168	561889	female
Se14.A	561782 r	male			
Se14.B	561781 f	female			
Sw17	562763 r	male			
Sw35	562763 r	male			
Sw37	562763 r	male			
Sw36	562763 r	male			
Sw101	562763 r	male			
Sw14	562763 r	male			
Se13	562350 r	male			
Sw124	562763 r	male			
A73.J2	563684 r	male			