No	Location	Part #	Gender	No	Location	Part #	Gender
A1.A	RJB	563975	male	A44.J1	FJB	563133	male
A2A	Left_Hand_Console	563984	male	A44.J2	FJB	563132	male
A4A.A	Service_Cmpt	562428	female	A44.J3	FJB	562957	male
A4A.B	Service_Cmpt	561188	female	A45.J1	FJB	563133	male
A5A	Service_Cmpt	562428	female	A45.J2	FJB	563132	male
A6	Rear_Axle_Cmpt	562427	male	A45.J3	FJB	562957	male
A7	Rear_Axle_Cmpt	563979	male	A46.J1	FJB	563133	male
A9.Cx1	FJB	564041	female	A46.J2	FJB	563132	male
A9.Cx2	FJB	563678	male	A46.J3	FJB	562957	male
A9.Cx3	FJB	564037	female	A47.J1	RightHandConsole	563133	male
A9.Cx4	FJB	564038	female	A47.J2	RightHandConsole	563132	male
A13.J1	FJB	562794	male	A47.J3	RightHandConsole	562957	male
A13.J2	FJB	562650	male	A48.J1	RightHandConsole	563133	male
A14A.A	Dash	562766	male	A48.J2	RightHandConsole	563132	male
A14A.B	Dash	562767	male	A48.J3	RightHandConsole	562957	male
A14A.C	Dash	562765	male	A49.J1	RJB	562767	male
A15	Dash	562464	male	A49.J2	RJB	563132	male
A18	FJB	562794	male	A49.J3	RJB	562957	male
A18.J2	FJB	562650	male	A50.J1	RJB	563133	male
A24	RightHandConsole	561889	female			563132	male
A24.A	RightHandConsole	561890	male	A50.J3	RJB	562957	male
A24.B	RightHandConsole	561566	female	A51.J1	RJB	563133	male
A27	ServiceCmpt.	562929	male	A51.J2	RJB	563132	male
A28	ServiceCmpt.	562928	male	A51.J3	RJB	562957	male
A29	Dash	562464	male	A52.J1	RJB	563133	male
A30	RightHandConsole	561889	female	A52.J2	RJB	563132	male
A30.A	RightHandConsole	561611	male	A52.J3	RJB	562957	male
A31.A	FJB	562676	male	A53.J1	RJB	563133	male
A31.B	FJB	562675	male	A53.J2	RJB	563132	male
A32.A	1stLuggCmpt.	561611	male	A53.J3	RJB	562957	male
A32.C	1stLuggCmpt.	561566	female	A54.J1	Evap.Cmpt.	563133	male
A36.JA	FJB	562767	male	A54.J2	Evap.Cmpt.	563132	male
A36.JB	FJB	562765	male			562957	male
A36.JC	FJB	562957	male	A55.J1	Dash	562767	male
A41.J1	FJB	562767	male	A55.J2	Dash	563132	male
A41.J2	FJB	563132	male	A55.J3	Dash	562957	male
A41.J3	FJB	562957	male	A56.J1	Slide-OutPanel	563133	male
A42.J1	FJB	562767	male	A56.J2	Slide-OutPanel	563132	male
A42.J2	FJB	563132	male	A56.J3	Slide-OutPanel	562957	male
A42.J3	FJB	562957	male	A57.J1	Slide-OutPanel	563133	male
A43.J1	FJB	562767	male	A57.J2		563132	male
A43.J2	FJB	563132	male	A57.J3		562957	male
A43.J3	FJB	562957	male		Slide-OutPanel	563133	male

SSEVOET	WIRING DIAGRAM	١		REVISION
FRE VUS 1	WIRING DIAGRAM	No:	D061160 Page G.1	03

No	Location	Part #	Gender	No	Location	Part #	Gender
A58.J2	Slide-OutPanel	563132	male	C3S	RJB	563593	male
A58.J3	Slide-OutPanel	562957	male	C3S	RJB	563590	female
A59.J1	Slide-OutPanel	563133	male	C4	ServiceCmpt.	563580	male
A59.J2	Slide-OutPanel	563132	male	C4	ServiceCmpt.	563581	female
A59.J3	Slide-OutPanel	562957	male	C5	FJB	563589	male
A60	Parcel_Rack_LH_1st_Cmpt	562767	male	C5	FJB	563590	female
A81A.JA	FJB	562767	male	C5S	FJB	563589	male
A81A.JB	FJB	562765	male	C5S	FJB	563590	female
A81A.JC	FJB	562957	male	C6	ServiceCmpt.	563582	male
A83A	FJB	564205	male	C6	ServiceCmpt.	563583	female
A96	FJB	564073	female	C7	Service_Cmpt	562581	female
A97	Dash	563226	male	C7	Service_Cmpt	562583	female
A100	Front_Axle_Cmpt	563758	female	C8	Service_Cmpt	563227	male
A101	Rear_Axle_Cmpt	563758	female	C8	Service_Cmpt	563614	female
A102	Rear_Axle_Cmpt	563758	female	C10	Engine_Cmpt	562581	male
A103	Dash	562070	female	C10	Engine_Cmpt	562583	female
A131.A	Engine_Cmpt	561782	male	C11	ServiceCmpt.	563580	male
A131.B	Engine_Cmpt	561781	female	C11	ServiceCmpt.	563581	female
A138	Cond_Cmpt	563787	male	C12	RJB	561986	male
A139	Dash	564501	male	C12	RJB	561987	female
Alt1D.A	Engine_Cmpt	563746	female	C13S	RightHandConsole	563593	male
Alt1D.B	Engine_Cmpt	560815	female	C13S	RightHandConsole	563590	female
Alt1D.C	Engine_Cmpt	564469	female	C13_plug	Right_Hand_Console	563589	male
Alt2D.A	Engine_Cmpt	563746	female	C13_socket	Right_Hand_Console	563590	female
Alt2D.B	Engine_Cmpt	560815	female	C15	5thLuggCmpt.	561646	male
Alt2D.C	Engine_Cmpt	564469	female	C15	5thLuggCmpt.	561645	female
B85	Engine_Cmpt	563815	male	C17	RJB	561986	male
B96.J1	Engine_Cmpt	563821	male	C17	RJB	561987	female
B96B	Engine_Cmpt	563823	male	C18	FJB	561986	male
B97	Engine_Cmpt	563816	male	C18	FJB	561987	female
B98.J1	Engine_Cmpt	563817	male	C19	RJB	561986	male
B115.J1	Engine_Cmpt	563818	female	C19	RJB	561987	female
B142B	Cond_Cmpt	563793	male	C20A	Engine_Cmpt	562485	male
C1	FJB	563589	male	C20A	Engine_Cmpt	562486	female
C1	FJB	563590	female	C20B	Engine_Cmpt	562485	male
C1S	FJB	563589	male	C20B	Engine_Cmpt	562486	female
C1S	FJB	563590	female	C21A	RJB	561646	male
C2	ServiceCmpt.	563580	male	C21A	RJB	561645	female
C2	ServiceCmpt.	563581	female	C21B	RJB	561646	male
C2A	FJB	563580	male	C21B	RJB	561645	female
C2A	FJB	563581	female	C22	RJB	561847	male
C3	RJB	563589	male	C22	RJB	561862	female
C3	RJB	563590	female	C24	Evap.Cmpt.	561690	male

BEVOET	WIRING DIAGRAM	١		REVISION
FRE VUS I	WIRING DIAGRAM	No:	D061160 Page G.2	03

No	Location	Part #	Gender	No		Part #	Gender
C24	Evap.Cmpt.	561566	female	C83	2ndLuggCmpt.	561668	male
C26	Cond_Cmpt	563580	male	C83	2ndLuggCmpt.	561551	female
C26	Cond_Cmpt	563581	female	C84	2ndLuggCmpt.	561668	male
C27	RJB	562005	male	C84	2ndLuggCmpt.	561551	female
C27	RJB	561714	female	C85	3rdLuggCmpt.	561668	male
C28	5thLuggCmpt.	561637	male	C85	3rdLuggCmpt.	561551	female
C28	5thLuggCmpt.	561636	female	C86	3rdLuggCmpt.	561668	male
C34	RightHandConsole	561986	male	C86	3rdLuggCmpt.	561551	female
C34	RightHandConsole	561987	female	C87	RearRoof	563618	male
C36	FJB	561986	male	C87	RearRoof	563616	female
C36	FJB	561987	female	C89	RearRoof	561581	male
C40	Dash	562485	male	C89	RearRoof	561582	female
C40	Dash	562486	female	C91	RJB	562285	male
C44_plug	FJB	561577	male	C91	RJB	562282	female
C44_socket	FJB	561605	female	C92	FJB	561986	male
C45	FJB	561643	male	C92	FJB	561987	female
C45	FJB	561642	female	C96	FJB	561643	male
C48	ServiceCmpt.	561690	male	C96	FJB	561642	female
C48	ServiceCmpt.	561566	female	C97	FJB	561640	male
C49A	FJB	562005	male	C97	FJB	561639	female
C49A	FJB	561714	female	C98	Engine_Cmpt	563817	male
C54	Engine_Cmpt	563580	male	C98	Engine_Cmpt	563830	female
C54	Engine_Cmpt	563581	female	C100	5thLuggCmpt.	563589	male
C64	Engine_Cmpt	563580	male	C100	5thLuggCmpt.	563590	female
C64	Engine_Cmpt	563581	female	C100S	5thLuggCmpt.	563589	male
C69	FJB	561583	male	C100S	5thLuggCmpt.	563590	female
C69	FJB	561585	female	C101	ServiceCmpt.	561690	male
C71	FJB	561646	male	C101	ServiceCmpt.	561566	female
C71	FJB	561645	female	C102	RJB	561690	male
C72	ServiceCmpt.	561646	male	C102	RJB	561566	female
C72	ServiceCmpt.	561645	female	C105		562581	male
C74	ServiceCmpt.	561645	female	C105	FJB	562583	female
C74	ServiceCmpt.	561646	male	C106_plug	FJB	562581	male
C75	4thLuggCmpt	561668	male	C106_socket	FJB	562583	female
C75	4thLuggCmpt	561551	female	C119A	Rear_Engine_Door	562581	male
C77	4thLuggCmpt	561668	male	C119A	Rear_Engine_Door	562583	female
C77	4thLuggCmpt	561551	female	C120A	Rear_Engine_Door	563580	male
C78	EngineCmpt.	561690	male	C120A	Rear_Engine_Door	563581	female
C78	EngineCmpt.	561566	female	C152	CondensorCmpt.	561611	male
C81	1stLuggCmpt.	561668	male	C152	CondensorCmpt.	561610	female
C81	4thLuggCmpt	561551	female	C171	FJB	561646	male
C82	1stLuggCmpt.	561668	male	C171		561645	female
C82	1stLuggCmpt.	561551	female	C172	ServiceCmpt.	561637	male

WIRING DIAGRAM	No:	D061160 Page G.3	REVISION 03
	WIRING DIAGRAM	WIRING DIAGRAM No:	WIRING DIAGRAM No: D061160 Page G.3

No	Location	Part #	Gender	No	Location	Part #	Gender
C172	ServiceCmpt.	561635	female	C397	RJB		male
C193	RJB	563589	male	C397	RJB	562282	female
	RJB	563590	female	C399	Engine_Cmpt	562477	male
C194	FJB	563589	male	C399	Engine_Cmpt	562479	female
C194	FJB	563590	female	C399A	Engine_Cmpt	562477	male
C200	FJB	561607	male	C399A	Engine_Cmpt	562479	female
C200	FJB	561606	female	C400_plug	EngineCmpt.	561782	male
C200B	Engine_Cmpt	562471	male	C400_socket	EngineCmpt.	561781	female
C200B	Engine_Cmpt	562348	female	C426	Engine_Cmpt	561611	male
C222	FJB	562477	male	C426	Engine_Cmpt	561610	female
C222	FJB	562479	female	C463	EngineCmpt.	562570	female
C223	FJB	563227	male	C463	EngineCmpt.	562571	male
C223	FJB	563614	female	C464	RJB	563180	male
C224	Dash	561637	male	C464	RJB	563347	female
C224	Dash	561636	female	C550	5thLuggCmpt.	561476	male
C225	FJB	562650	male	C550	5thLuggCmpt.	561477	female
C225	FJB	562649	female	C551	5thLuggCmpt.	561476	male
C228	EngineCmpt.	563227	male	C551	5thLuggCmpt.	561477	female
C228	EngineCmpt.	563614	female	C552	3rdLuggCmpt.	561476	male
C246	ServiceCmpt.	563090	male	C552	3rdLuggCmpt.	561477	female
C246	ServiceCmpt.	563091	female	C553	2ndLuggCmpt.	561476	male
C264A	Entrance_Door	563227	male	C553	2ndLuggCmpt.	561477	female
C264A	Entrance_Door	563614	female	C554	1stLuggCmpt.	561476	male
C266A	Entrance_Door	561640	male	C554	1stLuggCmpt.	561477	female
C266A	Entrance_Door	561639	female	C555	1stLuggCmpt.	561476	male
C269	RHConsole	563090	male	C555	1stLuggCmpt.		female
C269	RHConsole	563091	female	C556	5thLuggCmpt.	561476	male
C279	FJB	562477	male	C556	5thLuggCmpt.	561477	female
C279	FJB	562479	female	C557	3rdLuggCmpt.		male
C281	LeftHandConsole	560852	male	C557	3rdLuggCmpt.		female
C281	LeftHandConsole	560851	female	C558	4thLuggCmpt	561476	male
C290	5thLuggCmpt.	561668	male	C558	4thLuggCmpt		female
C290	5thLuggCmpt.	561551	female	C559	5thLuggCmpt.		male
C291	5thLuggCmpt.	561668	male	C559	5thLuggCmpt.	561477	female
C291	5thLuggCmpt.	561551	female	C617	Mirror_LH	563801	male
C330	FJB	561690	male	C617	Mirror_LH	563800	female
C330	FJB	561566	female	C618	Mirror_RH	563801	male
C342	EngineCmpt.	562485	male	C618	Mirror_RH	563800	female
C342	EngineCmpt.	562486	female	C717	RJB	561646	male
C360	Dash	561247	male	C717	RJB	561645	female
C360	Dash	561248	female	CC1	ServiceCmpt.	563227	male
C380	Dash	563180	male	CC1	ServiceCmpt.		female
C380	Dash	563347	female	CC2	ServiceCmpt.	563226	male

JJEVOET	WIRING DIAGRAM			REVISION
FRE VUS I	WIKING DIAGRAM	No:	D061160 Page G.4	03

No	Location	Part #	Gender	No	Location	Part #	Gender
CC2	ServiceCmpt.	563613	female	L69.A	Outside_3rd_Lugg_Door_LH	562155	male
CS01	Slide-OutPanel	563226	male	L70.A	Outside_3rd_Lugg_Door_LH	562155	male
CS01	Slide-OutPanel	563613	female	L72	Rear_Vehicle	562155	male
CS01S	Slide-OutPanel	563226	male	L74	Rear_Vehicle	562155	male
CS01S	Slide-OutPanel	563613	female	L75	Rear_Vehicle	562155	male
CS02	Slide-OutPanel	561643	male	L76	Rear_Engine_Door	562155	male
CS02	Slide-OutPanel	561641	female	L87A.A	Rear_Roof	561608	female
CS05	Slide-OutPanel	561847	male	L87A.B	Rear_Roof	562286	male
CS05	Slide-OutPanel	561862	female	L88A.A	Rear_Roof	561608	female
CS07	Slide-OutPanel	562581	male	L88A.B	Rear_Roof	562286	male
CS07	Slide-OutPanel	562583	female	L89A.A	Rear_Roof	561608	female
CSo8	Slide-OutPanel	562581	male	L89A.B	Rear_Roof	562286	male
CSo8	Slide-OutPanel	562583	female	L90A.A	Rear_Roof	561608	female
CSo9	Slide-OutPanel	562581	male	L90A.B	Rear_Roof	562286	male
CSo9	Slide-OutPanel	562583	female	L93.A	Rear_Vehicle	563069	female
CT2	EngineCmpt.	563226	male	L93.B	Rear_Vehicle	563069	female
CT2	EngineCmpt.	563613	female	L94.A	EngineCmpt.	563069	female
EI	Engine_Cmpt	563739	male	L94.B	EngineCmpt.	563069	female
L1	Service_Cmpt	562485	male	L95A	Outside_Front_LH	562485	male
L16	FrontRoof	562803	male	L95B	Outside_Front_LH	562485	male
L17	FrontRoof	562803	male	L96A	Outside_Front_RH	562485	male
L18A	Entrance_Door	562549	male	L96B	Outside_Front_RH	562485	male
L19	Entrance_Door	562549	male	L97.A	Outside_Front_LH	563069	female
L21.A	FrontRoof	561608	female	L97.B	Outside_Front_LH	563069	female
L21.B	FrontRoof	562286	male	L98A.A	Entrance_Door	563069	female
L22.A	FrontRoof	561608	female	L98A.B	Outside_Front_RH	563069	female
L22.B	FrontRoof	562286	male	L173	Engine_Cmpt	563590	female
L23.A	FrontRoof	561608	female	L174	Engine_Cmpt	563590	female
L23.B	FrontRoof	562286	male	L175	RJB	561247	male
L24.A	FrontRoof	561608	female	L176	5thLuggCmpt.	561247	male
L24.B	FrontRoof	562286	male	L177	5thLuggCmpt.	561247	male
L25.A	FrontRoof	561608	female	L178	3rdLuggCmpt.	561247	male
L25.B	FrontRoof	562286	male	L179	3rdLuggCmpt.	561247	male
L26.A	FrontRoof	561608	female	L180	2ndLuggCmpt.	561247	male
L26.B	FrontRoof	562286	male	L181	2ndLuggCmpt.	561247	male
L27.A	FrontRoof	561608	female	L182	1stLuggCmpt.	561247	male
L27.B	FrontRoof	562286	male	L183	1stLuggCmpt.	561247	male
L63	Outside_Front_RH	562155	male	L184	ServiceCmpt.	561247	male
L64	Outside_Front_RH	562155	male	L185.A	Service_Cmpt	562651	female
L65	Outside_Front_LH	562155	male	L185.B	Service_Cmpt	562290	female
L66	Outside_Front_LH	562155	male	L186.A	Service_Cmpt	562651	female
L67.A	Outside_3rd_Lugg_Door_RH	562155	male	L186.B	Service_Cmpt	562290	female
L68.A	Outside_3rd_Lugg_Door_RH	562155	male	L187.A	Engine_Cmpt	561690	male

7	R	E	V	S	0

No	Location	Part #	Gender	No	Location	Part #	Gender
L189	Outside_Front_RH	562069	male	Mo37	4th_Lugg_Cmpt	564161	male
L190	Outside_Front_LH	562069	male	Mo40	1stLuggCmpt.	561477	female
L193.A	Dash	560488	female	Mo44	5th_Lugg_Cmpt	561477	female
L193.B	Dash	560488	female	Mo50	ServiceCmpt.	561782	male
L194.A	Dash	562019	female	Mo51	1stLuggCmpt.	561690	male
L194.B	Dash	560488	female	Mo53	RJB	561248	female
L195.A	Dash	560488	female	Mo54	Service_Cmpt	562474	male
L195.B	Dash	560488	female	Mo55.A	Rr_RH_Slideout	561967	male
L199	EngineCmpt.	562471	male	Mo56	5th_Lugg_Cmpt	561477	female
L199OP.A	EngineCmpt.	564128	female	Mo57.A	Front_RH_Slideout	561967	male
L200	EngineCmpt.	562471	male	Mo58	1st_Lugg_Cmpt	561477	female
L200_OP.A	EngineCmpt.	564128	female	MONITOR	Dash	561247	male
L203	RightHandConsole	561690	male	MoSo1.A	Front_LH_Slideout	561967	male
L205	Evap.Cmpt.	562485	male	MOSO2.A	Rr_LH_Slideout	561967	male
L211	Entrance_Door	562549	male	Pot1.A	Dash	560488	female
L282	Rear_Axle_Cmpt	561690	male	Pot1.B	Dash	560488	female
L285	Dash	561247	male	Pot1.C	Dash	560488	female
L287	4thLuggCmpt	561247	male	R3	RJB	563409	male
L288	4thLuggCmpt	561247	male	R10	Evap.Cmpt.	563409	male
L290	Engine_Door	562565	female	R12	Evap.Cmpt.	563409	male
L291	Engine_Door	562565	female	R17	RJB	564210	male
L298	Engine_Cmpt	563590	female	R18	FJB	564210	male
L302	Outside_Front_RH	562789	male	R19	FJB	564210	male
L303	Outside_Front_LH	562789	male	R21	RJB	561183	male
L350	Rr_Axle_Cmpt	562350	male	R23	RightHandConsole	561183	male
Mo3	Dash	561667	female	R24	FJB	561183	male
Mo4	Dash	562076	male	R25	RJB	561183	male
Mo7	Cond_Cmpt	563691	male	R29	RJB	563409	male
Mo8	Cond_Cmpt	563691	male	R30	RJB	561183	male
Mo12	Evap.Cmpt.	561690	male	R31	RJB	561183	male
Mo15	Over_Head_Driver_Area	560900	female	R32	RJB	561183	male
Mo16	Over_Head_Driver_Area	560900	female	R33	RJB	561183	male
Mo17	LeftHandConsole	563626	male	R34	RJB	564210	male
Mo18	Fr_Service_Door	562474	male	R36	FJB	561183	male
Mo19	Fr_Service_Door	562474	male	R37	FJB	561183	male
Mo20	Fr_Service_Door	562474	male	R41	FJB	561183	male
Mo21	FrontRoof	561186	male	R42	FJB	561183	male
Mo22	RightHandConsole	561186	male	R43	FJB	561183	male
Mo24	RightHandConsole	562348	female	Res3	RJB	563590	female
Mo25	RightHandConsole	562348	female	Res4	RightHandConsole	563590	female
Mo26A	Entrance_Door	564161	male	Res6	FJB	563590	female
Mo27	Cond_Cmpt	563691	male	Res7.A	FJB	563590	female
Mo28	Cond_Cmpt	563691	male	Res15	RJB	561782	male

2	RE	VC) 5	0

No	Location	Part #	Gender	No	Location	Part #	Gender
Res18.A	ExhaustCmpt	563590	female	Se36	Engine_Cmpt	563628	female
Res31	Cond_Cmpt	562350	male	Se37	Front_Axle_RH	641132	female
Res32	Cond_Cmpt	563764	female	Se38	Front_Axle	641132	female
RSo1.A	Slide-OutPanel	562168	female	Se39	Rear_Axle_LH	641132	female
RSo1.B	Slide-OutPanel	562168	female	Se40	Rear_Axle_LH	641132	female
RSo2.A	Slide-OutPanel	562168	female	Se45	ServiceCmpt.	563409	male
RSo2.B	Slide-OutPanel	562168	female	Se46	AboveRearAxle	562348	female
RSo3.A	Slide-OutPanel	562168	female	Se49	Engine_Cmpt	563677	male
RSo3.B	Slide-OutPanel	562168	female	Se50	Engine_Cmpt	562426	male
RSo4.A	Slide-OutPanel	562168	female	Se52.A	RightHandConsole	560488	female
RSo4.B	Slide-OutPanel	562168	female	Se52.B	RightHandConsole	560488	female
RSo5.A	Slide-OutPanel	562168	female	Se53	Service_Cmpt	563159	female
RSo5.B	Slide-OutPanel	562168	female	Se54	Service_Cmpt	563159	female
RSo6.A	Slide-OutPanel	562168	female	Se55	Service_Cmpt	563159	female
RSo6.B	Slide-OutPanel	562168	female	Se60	Service_Cmpt	563409	male
RSo7.A	Slide-OutPanel	562168	female	Se63	Rear_Axle_Cmpt	641132	female
RSo7.B	Slide-OutPanel	562168	female	Se64	Rear_Axle_Cmpt	641132	female
RSo8.A	Slide-OutPanel	562168	female	Se65	Dash	564042	female
RSo8.B	Slide-OutPanel	562168	female	Se66	Front_Axle_Cmpt	564039	female
Se11.A	Cond.Cmpt.	560082	male	Se67	Front_Axle_Cmpt	563159	female
Se11.B	Cond.Cmpt.	560082	male	Se68	Rear_Axle_Cmpt	563159	female
Se11.C	Cond.Cmpt.	560082	male	Se69	Front_Axle_Cmpt	563159	female
Se12	EngineCmpt.	561690	female	SESO1	SlideOut_Panel	563159	male
Se13	Engine_Cmpt	562350	male	SESO2_SESO3	SlideOut_Fr_LH	562479	female
Se14.A	Driver_Area	561782	male		SlideOut_Rr_LH	562479	female
Se14.B	Driver_Area	561781	female		SlideOut_Rr_RH	562479	female
Se16A.A	Entrance_Door	562651	female	SESO9_SESO10	SlideOut_Fr_RH	562479	female
Se16A.B	Entrance_Door	562651	female	So7	ServiceCmpt.	561566	male
Se17.A	RightHandConsole	562019	female	So8	ServiceCmpt.	563204	female
Se17.B	RightHandConsole	562019	female	So9	Engine_Cmpt	561690	male
Se19	Service_Cmpt	563677	male	So9OP.A	Engine_Cmpt	564127	female
Se20	Evap_Cmpt	562426	male	So11	Cond.Cmpt.	561566	female
Se21	Dash	561248	female	So13	Evap.Cmpt.	563204	female
Se23	EngineCmpt.	563159	male	So21	Front_Axle_Cmpt	564046	female
Se24	EngineCmpt.	563159	male	So22	Front_Axle_Cmpt	564046	female
Se25	PassengerArea	561248	female	So23	Rear_Axle_Cmpt	564046	female
Se29	EngineCmpt.	561566	female	So24	Rear_Axle_Cmpt	564046	female
Se30	Engine_Door	562877	female	So26	ServiceCmpt.	641385	male
Se31	Compr_Door	562877	female	So27	Rear_Axle_Cmpt	564045	male
Se32	EngineCmpt.	563057	male	So34	EngineCmpt.	561690	male
Se33	EngineCmpt.	562856	male	So38	1stLuggCmpt.	561566	female
Se34	EngineCmpt.	563057	male	So50	Rear_Axle_Cmp	564046	female
Se35	EngineCmpt.	563057	male	So51	Rear_Axle_Cmp	564046	temale

PEVOET	WIRING DIAGRAM	١		REVISION
FRE VUS 18	WIKING DIAGRAM	No:	D061160 Page G.7	03

No	Location	Part #	Gender	No	Location	Part #	Gender
So52	Front_Axle_Cmpt	564045	female	Sw49.B	2ndLuggCmpt.	562403	female
SoSo1	SlideOut_Panel	641385	male	Sw50.A	2ndLuggCmpt.	562403	female
SoSo2	SlideOut_Panel	641385	male	Sw50.B	2ndLuggCmpt.	562403	female
SoSo3	SlideOut_Panel	641385	male	Sw51.A	1stLuggCmpt.	562403	female
SOSO4	SlideOut_Panel	641385	male	Sw51.B	1stLuggCmpt.	562403	female
SoSo5	SlideOut_Panel	641385	male	Sw52	1stLuggCmpt.	562403	female
SoSo6	SlideOut_Panel	641385	male	Sw52.B	1stLuggCmpt.	562403	female
SoSo7	SlideOut_Panel	564045	female	Sw58	EngineCmpt.	562581	male
SoSo8	SlideOut_Panel	564045	female	Sw59	EngineCmpt.	562485	male
spBar1	Engine_Cmpt	564135	male	Sw63A		562763	male
spBar2.J1	Engine_Cmpt	564135	male	Sw64.A	Service_Cmpt	560815	female
Sw1.C258	Dash	561188	female	Sw64.B	Service_Cmpt	560815	female
Sw1.C259	Dash	561186	male	Sw82.A	RJB	561457	female
Sw2	Dash	562763	male	Sw82.B	RJB	561457	female
Sw3	Dash	562763	male	Sw82.C	RJB	561457	female
Sw4	Dash	562763	male	Sw82.D	RJB	561457	female
Sw5	Dash	562763	male	Sw83.A	Dash	560082	female
Sw6	Dash	562763	male	Sw83.B	Dash	560815	female
Sw7.A	Cond.Cmpt.	562403	female	Sw83.C	Dash	560082	female
Sw7.B	Cond.Cmpt.	562403	female	Sw83.D	Dash	560815	female
Sw11A	LH_Console	562763	male	Sw85	LeftHandConsole	562749	male
Sw14	Dash	562763	male	Sw99	Dash	562763	male
Sw16	Dash	562763	male	Sw100	Dash	562763	male
Sw17	Dash	562763	male	Sw102	Dash	562763	male
Sw18A	Dash	562763	male	Sw103A	LH_Console	562763	male
Sw24	Dash	562763	male	Sw104	Dash	562763	male
Sw35	LH_Console	562763	male	Sw106	Entrance_Door	561637	male
Sw38	LeftHandConsole	562763	male	Sw107.A	LH_Console	561457	female
Sw39.A	RJB	562403	female	Sw107.B	LH_Console	561457	female
Sw39.B	RJB	562403	female	Sw107.C	LH_Console	561457	female
Sw40	LeftHandConsole	561690	male		LH_Console	561457	female
Sw41	LeftHandConsole	562749	male	Sw107.E	LH_Console	561457	female
Sw44.A	FJB	562403	female	Sw107.F	LH_Console	561457	female
Sw44.B	FJB	562403	female	Sw107.G	LH_Console	561457	female
Sw45.A	5thLuggCmpt.	562403	female	Sw107.H	LH_Console	561457	female
Sw45.B	5thLuggCmpt.	562403	female	Sw107.J	LH_Console	561457	female
Sw46.A	5thLuggCmpt.	562403	female	Sw107.K	LH_Console	561457	female
Sw46.B	5thLuggCmpt.	562403	female	Sw108	LeftHandConsole	562763	male
Sw47.A	3rdLuggCmpt.	562403	female	Sw116.A	4thLuggCmpt	560079	female
Sw47.B	3rdLuggCmpt.	562403	female	Sw116.B	4thLuggCmpt	560079	female
Sw48.A	3rdLuggCmpt.	562403	female	Sw117.A	5thLuggCmpt.	560079	female
Sw48.B	3rdLuggCmpt.	562403	female	Sw117.B	5thLuggCmpt.	560079	female
Sw49.A	2ndLuggCmpt.	562403	female	Sw119	Dash	562763	male

7	R	E	V	S	0

No	Location		Gender		
	DriverArea	562237	female		
	PassengerArea		male		
	4thLuggCmpt		female		
	4thLuggCmpt		female		
	Dash		male		
	SlideOut_Fr_LH	561552	female		
	SlideOut_Rr_LH		female		
SwSo3	SlideOut_Rr_RH		female		
SwSo4	SlideOut_Fr_RH		female		
	FJB		male		
VECF2	FJB		male		
VECF3	FJB		male		
VECF4	FJB		male		
	FJB	563448	male		
VECF10	FJB		male		
VECF11	FJB		male		
	FJB	563187	male		
	RJB	563186	male		
	RJB	563183	male		
	RJB		male		
VECR4	RJB	563182	male		
VECR9	RJB	563448	male		
VECR10	RJB	563181	male		
VECR11	RJB	563184	male		
VECR12	RJB	563187	male		
Y80	Engiene_Cmpt	563789	male		
Y81	Cond_Cmpt	563793	male		
			Ì		
			<u> </u>		

JJEVOET	WIRING DIAGRAM			REVISION
FREVUS 1	WIRING DIAGRAM	No:	D061160 Page G.9	03